



III. RECOMMENDATIONS OF REPAIRS TO TOWN OWNED BRIDGES

The following is a list, by bridge, of repairs that SELLS recommends to be immediate priorities. These repairs are all associated with extending the long term structural capacity and/or upgrading significantly substandard safety features.

Bridge No. A-02-007 (Lawsbrook Road over Fort Pond Brook)

SELLS recommends that the current steel W-beam guardrail/bridge rail be replaced in its entirety with a Modified Thrie Beam Bridge Rail and repairs be done to the concrete safety curbs. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately **\$44,000**.

Bridge No. A-02-008 (River Street over Fort Pond Brook at Carriage Drive)

SELLS recommends that the corrugated steel deck arch and lower connection plates be cleaned and coated with a new protective coating, particularly at the lower ends where the steel plate meets the concrete abutments. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately **\$41,000**.

Bridge No. A-02-009 (Brook Street over Nashoba Brook)

SELLS recommends that the steel corrugated pipe arch culverts be cleaned and coated with a new protective coating. Also, voids between the headwalls and pipe arches shall be filled to prevent the infiltration of water behind the pipe arches. Lastly, the stone masonry bridge rail and headwalls shall be repointed to fill the large gaps in the mortar. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately **\$92,000**.

Bridge No. A-02-010 (Parker Street over Fort Pond Brook)

SELLS recommends that the current steel W-beam guardrail/bridge rail be replaced in its entirety with a Modified Thrie Beam Bridge Rail and the steel corrugated deck arch and lower connection plates be cleaned and coated with a new protective coating, particularly at the lower ends where the steel plate meets the concrete abutments. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately **\$87,000**.

Bridge No. A-02-011 (Wetherbee Street over Nashoba Brook)

SELLS recommends that no work be done to this bridge at this time. The repairs that are recommended to be done to this structure would provide minimal benefits at this time. The Town should continue to monitor MassHighway Bridge Inspection Reports for changes to the bridge's condition.



Bridge No. A-02-018 (Concord Road over Nashoba Brook)

SELLS recommends that no work be done to this bridge at this time. The repairs that are recommended to be done to this structure would provide minimal benefits at this time. The Town should continue to monitor MassHighway Bridge Inspection Reports for changes to the bridge's condition.

Repairs are needed to the channel walls downstream from the bridge. As previously mentioned, these walls may be beyond the Town's Right of Way (owned by others.) Therefore, there may be a question as to whether the Town is responsible for maintenance of these walls.

Bridge No. A-02-020 (River Street over Fort Pond Brook at Merriam Lane)

SELLS recommends that the steel corrugated pipe culverts be cleaned and coated with a new protective coating. Also, voids between the headwalls and pipe arches shall be filled to prevent the infiltration of water behind the pipe arches. Riprap shall also be placed at the culvert ends to prevent undermining. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately \$100,000.

Bridge No. A-02-021 (River Street over Fort Pond Brook at Vanderbilt Road)

SELLS recommends that the steel corrugated pipe arch culverts be cleaned and coated with a new protective coating. Also, voids between the headwalls and pipe arches shall be filled to prevent the infiltration of water behind the pipe arches. Riprap shall also be placed at the culvert ends to prevent undermining and the failed section of the Southwest wingwall should be rebuilt. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately \$74,000.

Bridge No. A-02-022 (Stow Street over Fort Pond Brook)

SELLS recommends that the remaining concrete be removed from the bottom portion of the concrete encased steel beams and repairs be done to the faces of both abutments and both faces of the pierwall. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately \$26,000.

Bridge No. A-02-023 (Martin Street over Fort Pond Brook)

SELLS recommends that the steel corrugated pipe arch culverts be cleaned and coated with a new protective coating, weld/fasten steel corrugated plates over the areas where there is 100% section loss (holes) and severe rusting and steel delamination, place a reinforced concrete paved invert in both pipe arches, fill the voids between the headwalls and the pipe arches to prevent the infiltration of water behind the pipe arches and place riprap at both ends to prevent undermining. Based on the recommended repairs, the preliminary construction cost estimate to accomplish this work is approximately \$88,000.



IV. PRIORITY OF REPAIRS TO TOWN OWNED BRIDGES

The information provided above for the recommended repairs to the ten (10) Town Owned Bridges shows that repairs will be needed to a majority of the bridge structures to extend their service life. It shall be noted that the cost of water control for the repairs to be performed "in-the-dry" as well as for protection of the waterway is a significant cost for each of the bridge structures. In fact, the cost of water control is the basis for limiting our recommendations on several of the bridges. It shall also be noted that the water control measures, repointing of the stone masonry walls and other bridge repairs may require temporary easements and/or rights of entry from adjacent property owners at each of the bridge locations. The following is a priority list, by bridge, that indicates what SELLS believes should be the Town's approach to repairs on these structures. There may of course be savings by grouping similar work by repair/bridge type. For example, SELLS recommends that the Town's top priority should be the corrugated steel pipe culvert structures and in particular repairing and replacing the coating of these pipes as this is the primary structural member for these bridges.

1. Bridge No. A-02-023 (Martin Street over Fort Pond Brook) – Repairing the holes in the pipes, replacing the protective coating and placing a concrete invert should be the Town's top priority. These repairs are essential in order to ensure the current load carrying capacity of the structure.
2. Bridge No. A-02-009 (Brook Street over Nashoba Brook) – Replacing the protective coating and sealing the voids around the pipe ends is a high priority for this structure and should be addressed immediately.
3. Bridge No. A-02-021 (River Street over Fort Pond Brook at Vanderbilt Road) – Replacing the protective coating and sealing the voids around the pipe ends is a high priority for this structure and should be addressed immediately.
4. Bridge No. A-02-020 (River Street over Fort Pond Brook at Merriam Lane) – Replacing the protective coating and sealing the voids around the pipe ends is a high priority for this structure and should be addressed immediately.
5. Bridge No. A-02-008 (River Street over Fort Pond Brook at Carriage Drive) – Replacing the protective coating, primarily at the arch ends, is a moderate priority for this structure and should be addressed. However, it is not as critical as the corrugated pipes since the arch ends are not constantly exposed to water and do not exhibit the same level of deterioration even though this structure is significantly older than the corrugated pipe bridges.
6. Bridge No. A-02-022 (Stow Street over Fort Pond Brook) – This structure requires moderate repairs to the abutments and pierwall that can be accomplished for a relatively low cost of construction. However, there is already a full set of bridge replacement drawings for this bridge. SELLS recommends that these drawings, through the Town and MassHighway, be revisited to pursue future replacement of the bridge through MassHighway's Footprint Bridge Program.
7. Bridge No. A-02-010 (Parker Street over Fort Pond Brook) – This structure requires minor repairs to the deck arch and abutments without much benefit. It is



- recommended that the substandard bridge rail be replaced to address safety concerns and the Town seek the aid of MassHighway for possible future replacement.
8. Bridge No. A-02-007 (Lawsbrook Road over Fort Pond Brook) – This structure requires minor repairs to the deck and concrete “T” beams. The cost of water control would be expensive and difficult to accomplish and therefore the repairs needed on the underside of the bridge are not recommended considering the limited benefit they would provide. It is recommended that the existing substandard bridge rail be replaced to address a safety concern and the Town seek the aid of MassHighway for possible future replacement considering the age and condition of this structure.
 9. Bridge No. A-02-011 (Wetherbee Street over Nashoba Brook) – This structure requires minor repairs that will provide minimal benefits to the long term life of the structure and are therefore not recommended at this time because of the high cost associated with water control.
 10. Bridge No. A-02-018 (Concord Road over Nashoba Brook) – This structure requires minor repairs that will provide minimal benefits to the long term life of the structure and are therefore not recommended at this time because of the high cost associated with water control.

V. WETLAND PERMITTING DISCUSSION

Work will be required in the waterway at six (6) of the eight (8) recommended bridge locations to accomplish the necessary repairs. The water control measures shown in the Plans represent current methods used by MassHighway in diverting water so that work can be accomplished “in-the-dry” and so that sediments can be contained. There will be temporary impacts to Land Under Water as a result of installing cofferdams to accomplish repairs “in-the-dry.” In addition, there will be permanent impacts at those bridges where new riprap is proposed. These permanent impacts are limited to approximately 150 SF to 250 SF at each of the three (3) bridges where riprap is recommended.

VI. PRELIMINARY CONSTRUCTION COST ESTIMATE

The total construction cost, for all ten (10) Town Owned Bridges, at the Phase I - Preliminary Report design level is estimated to be approximately **\$875,000**, which cost does not include the cost for any utility work or right-of-way acquisitions. However, based on the recommendations for repairs from SELLS, the total construction cost estimate for the repairs that will be beneficial to the long term life of the bridge is approximately **\$552,000**. (See Appendix A for item summary sheets for each bridge structure)

MASSACHUSETTS HIGHWAY DEPARTMENT
STRUCTURES INSPECTION FIELD REPORT

2-DIST
03

B.I.N.
255

ROUTINE ARCH INSPECTION

BR. DEPT. NO.
A-02-008

CITY/TOWN ACTON		8-STRUCTURE NO. A02008-255-MUN-NBI	11-Kilo. POINT 001.288	41-STATUS A:OPEN	90-ROUTINE INSP. DATE DEC 5, 2005
07-FACILITY CARRIED HWY RIVER ST		MEMORIAL NAME/LOCAL NAME	27-YR BUILT 1937	106-YR REBUILT 0000	YR REHABD (NON 106) 0000
06-FEATURES INTERSECTED WATER FORT POND BROOK		26-FUNCTIONAL CLASS Urban Local	DIST. BRIDGE INSPECTION ENGINEER L. A. Gauthier		
43-STRUCTURE TYPE Steel Arch - Deck		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER J. Read	PROJ MGR Transystems
107-DECK TYPE Not applicable		WEATHER Cloudy	TEMP. (air) -5°C	TEAM MEMBERS T. TAYLOR	

ITEM 55		
DECK	N	DEF
1. Wearing surface	7	-
2. Deck Condition	N	-
3. Spandrel Fill	7	-
4. Curbs	6	M-P
5. Median	N	-
6. Sidewalks	N	-
7. Parapets	7	-
8. Railing	7	-
9. Anti Missile Fence	N	-
10. Drainage System	N	-
11. Lighting Standards	N	-
12. Utilities	N	-
13. Deck Joints	N	-
14.	N	-
15.	N	-
16.	N	-

ITEM 59		
SUPERSTRUCTURE	7	DEF
1. Arch/Arch Ring	7	-
2. Keystone Area	N	-
3. Stringers	N	-
4. Floorbeams	N	-
5. Spandrel Walls	7	-
6. Spring Lines	6	M-P
7. Diaphragms/Cross Frames	N	-
8. Conn Plt's, Gussets & Angles	N	-
9. Pin & Hangers	N	-
10. Masonry Joints	7	-
11. Rivets & Bolts	6	M-P
12. Welds	N	-
13. Deformation/Flattening	7	-
14. Member Alignment	7	-
15. Paint/Coating	7	-
16.	N	-

ITEM 60			
SUBSTRUCTURE	7	DEF	
1. Abutments	Dive	Cur	7
a. Pedestals	N	N	-
b. Bridge Seats	N	N	-
c. Backwalls	N	N	-
d. Breastwalls	N	7	-
e. Wingwalls	N	6	M-P
f. Slope Paving/Rip-Rap	N	N	-
g. Pointing	N	6	M-P
h. Footings	N	7	-
i. Piles	N	N	-
j. Scour	N	7	-
k. Settlement	N	8	-
l.	N	N	-
m.	N	N	-
2. Piers or Bents			N
a. Pedestals	N	N	-
b. Caps	N	N	-
c. Columns	N	N	-
d. Stems/Webs/Pierwalls	N	N	-
e. Pointing	N	N	-
f. Footing	N	N	-
g. Piles	N	N	-
h. Scour	N	N	-
i. Settlement	N	N	-
j.	N	N	-
k.	N	N	-
3. Pile Bents			N
a. Pile Caps	N	N	-
b. Piles	N	N	-
c. Diagonal Bracing	N	N	-
d. Horizontal Bracing	N	N	-
e. Fasteners	N	N	-

CURB REVEAL (In millimeters)

N	S
0	25

Year Painted **1990**

COLLISION DAMAGE: Please explain
 None (X) Minor () Moderate () Severe ()

LOAD DEFLECTION: Please explain
 None (X) Minor () Moderate () Severe ()

LOAD VIBRATION: Please explain
 None (X) Minor () Moderate () Severe ()

APPROACHES		
	N	DEF
a. Appr. pavement condition	7	-
b. Appr. Roadway Settlement	8	-
c. Appr. Sidewalk Settlement	N	-
d. Approach Utilities	H	-

OVERHEAD SIGNS (Attached to bridge)		
(Y/N)	N	DEF
a. Condition of Welds	N	-
b. Condition of Bolts	N	-
c. Condition of Signs	N	-

Any Fracture Critical Member: (Y/N) **N**

Any Cracks: (Y/N) **N**

UNDERMINING (Y/N) If YES please explain **N**

COLLISION DAMAGE:
 None (X) Minor () Moderate () Severe ()

I-60 (Dive Report): **N** I-60 (This Report): **7**

93B-UW (DIVE) Insp **00/00/00**

CITY/TOWN ACTON	B.I.N. 255	BR. DEPT. NO. A-02-008	8-STRUCTURE NO. A02008-255-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	--	---------------------------------------

ITEM 61 7

CHANNEL & CHANNEL PROTECTION

	Dive	Cur	DEF
1. Channel Scour	N	7	-
2. Embankment Erosion	N	7	-
3. Debris	N	7	-
4. Vegetation	N	7	-
5. Utilities	N	N	-
6. Rip-Rap/Slope Protection	N	7	-
7. Aggradation	N	7	-
8. Fender System	N	N	-

STREAM FLOW VELOCITY:
Tidal () High () Moderate (X) Low () None ()

ITEM 61 (Dive Report): N ITEM 61 (This Report) 7

93b-UW INSP. DATE:

ITEM 56 TRAFFIC SAFETY

	TR	COND	DEF
A. Bridge Railing	0	7	-
B. Transitions	0	0	-
C. Approach Guardrail	1	7	-
D. Approach Guardrail Ends	1	7	-

WEIGHT POSTING Not Applicable X

Actual Posting: N N N N

Recommended Posting: N N N N

Waived Date: EJDNT Date:

Signs in Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility

At bridge		Other Advance	
E	W	E	W
/	/	/	/

CLEARANCE POSTING Not Applicable X

Actual Field Measurement: ft in

Posted Clearance: ft in

Signs in Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility

At bridge		Advance	
N	S	N	S
/	/	/	/

ACCESSIBILITY (Y/N/P)

	Needed	Used
Lift Bucket	N	N
Ladder	N	N
Boat	N	N
Waders	Y	Y
Inspector 50	N	N
Rigging	N	N
Staging	N	N
Traffic Control	N	N
RR Flagger	N	N
Police	N	N
Other:		
	N	N

TOTAL HOURS

PLANS (Y/N):

(V.C.R.) (Y/N):

TAPE#: _____

List of field tests performed:

RATING

Rating Report (Y/N)

Date:

(To be filled out by DBIE)

Request for Rating or Rerating (Y/N)

REASON: _____

If YES please give priority:
HIGH () MEDIUM () LOW ()

CONDITION RATING GUIDE
(For Items 58, 59, 60 and 61)

CODE	CONDITION	DEFECTS
N	NOT APPLICABLE	
G 9	EXCELLENT	Excellent condition.
G 8	VERY GOOD	No problem noted.
G 7	GOOD	Some minor problems.
F 6	SATISFACTORY	Structural elements show some minor deterioration.
F 5	FAIR	All primary structural elements are sound but may have minor section loss, cracking, spalling or scour
P 4	POOR	Advance section loss, deterioration, spalling or scour.
P 3	SERIOUS	Loss of section, deterioration, spalling or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.
C 2	CRITICAL	Advance deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C 1	"IMMINENT" FAILURE	Major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put it back in light service.
0	FAILED	Out of service - beyond corrective action.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency- Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor pot holes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.

S= Severe/Major Deficiency- Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroded rebars, Considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.

C-S= Critical Structural Deficiency - A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.

C-H= Critical Hazard Deficiency - A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Loose concrete hanging down over traffic or pedestrians, A hole in a sidewalk that may cause injuries to pedestrians, Missing section of bridge railing, etc.

URGENCY OF REPAIR:

I = Immediate- Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her.

A = ASAP- Action/Repair should be initiated by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) upon receipt of the Inspection Report.

P = Prioritize- Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available.

CITY/TOWN ACTON	B.I.N. 255	BR. DEPT. NO. A-02-008	8.-STRUCTURE NO. A02008-255-MUN-NBI	INSPECTION DATE DEC 6, 2005
--------------------	---------------	---------------------------	--	--------------------------------

REMARKS

BRIDGE ORIENTATION

River Street travels east and west over the Fort Pond Brook which flows from south to north.

GENERAL REMARKS

The length of bridge rail and wingwalls does not agree with the 1936 plans. The structure has been rehabilitated but the date of rehabilitation is unknown. The corrugated plate arch is galvanized and the length of bridge rails and parapets is more than 25 ft. longer than the length shown on the plans.

ITEM 58 - DECK

Item 58.4 - Curbs

The curbs consist of beveled mortar which is on top of the spandrel wall cap stone. There are a few spot locations where this mortar has broken off exposing the spandrel wall cap stone primarily on the south side. (See Photo 1.) During the day of inspection the edge of roadway on both sides had a covering of snow that hid the curb area. Where the snow cover was removed and the curb was exposed the condition was observed to be similar to that reported in 2003. Therefore the curb reveals reported in 2003 have been carried forward.

The 1936 record plans for this structure indicate the distance from the bottom of the cap stone (on the masonry bridge rail) to the top of the spandrel wall (base of beveled mortar curb) is 2 ft. - 2 in. This distance could be checked and verified during a future inspection, and then used to monitor the addition of dead load due to future pavement overlays.

Item 58.8 - Railing

The bridge rails consist of stone masonry blocks set in mortar. There are spot locations of mortar popouts primarily in the south bridge rail. (See Photo 2.)

APPROACHES

Approaches a - Appr. pavement condition

The west approach pavement has two diagonal transverse cracks in the center of the roadway which are parallel to the arch barrel. There are markings on the pavement which indicate that there may be a utility under the pavement in this area. The east approach pavement has a longitudinal crack in the eastbound travel lane which is parallel to and 5 to 6 ft. north of the south edge of pavement.

Approaches d - Approach Utilities

On the west approach pavement, utility paint markings were observed on the approach, west of the stone masonry bridge rail ends. The paint markings indicated that the utility alignment diagonally traversed the roadway from south to north when moving east. No determination could be made as to whether the utility crossed the bridge longitudinally in the spandrel fill above the arch.

ITEM 59 - SUPERSTRUCTURE

Item 59.6 - Spring Lines

On the west side in the center of the barrel there is a bow of 1 to 2 in. above the spring line. The steel seat plate for the corrugated plate arch is rusted at the southeast, southwest and northwest quadrants. (See Photo 3.)

Item 59.11 - Rivets & Bolts

There are approximately 5 spot locations of bolt and nut rusting throughout the barrel. In one location there is full section loss of the nut. The rest of the bolts are in good condition.

CITY/TOWN ACTON	B.I.N. 255	BR. DEPT. NO. A-02-008	3-STRUCTURE NO. A02008-255-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	--	---------------------------------------

REMARKS

ITEM 60 - SUBSTRUCTURE

Item 60.1.e - Wingwalls

There is an 8 ft. wide and 4 ft. tall area with missing mortar in the northeast wingwall. The voids in the mortar were found to be approximately 1 ft. deep. (See Photo 4.)

Item 60.1.g - Pointing

There is an area in the northeast wingwall where the pointing is missing. See Item 60.1.e - Wingwalls.

TRAFFIC SAFETY

Item 36b - Transitions

There are no transitions between the approach guardrail and the stone masonry bridge rail.

Photo Log

- Photo 1 : South curb center span.
- Photo 2 : South bridge rail, southeast quadrant.
- Photo 3 : Southwest end of barrel.
- Photo 4 : Northeast wingwall.
- Photo 5 : River Street facing east.
- Photo 6 : North elevation.

CITY/TOWN ACTON	B.I.N. 255	BR. DEPT. NO. A-02-008	8.-STRUCTURE NO. A02008-255-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS



Photo 1: South curb center span.



Photo 2: South bridge rail, southeast quadrant.

CITY/TOWN ACTON	B.I.N. 255	BR. DEPT. NO. A-02-008	8.-STRUCTURE NO. A02008-255-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS



Photo 3: Southwest end of barrel.



Photo 4: Northeast wingwall.

CITY/TOWN ACTON	B.I.N. 255	BR. DEPT. NO. A-02-008	8.-STRUCTURE NO. A02008-255-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS



Photo 5: River Street facing east.



Photo 6: North elevation.

Report Date: October 23, 2007

State Information				Classification				Code	
BDEPT#	A02008	Agency Br.No.		(112) NBIS Bridge Length				Y	
Town	Acton			(104) Highway System				N	
B.I.N.	266	AASHTO	069.7	(26) Functional Class -	Urban Local			19	
Identification				FHWA Select List	Y	(100) Defense Highway		0	
(6) Structure Number	A02008255MUNNBI			(101) Parallel Structure				N	
(5) Inventory Route	151000000			(102) Direction of Traffic -	2-way traffic			2	
(2) State Highway Department District	03			(103) Temporary Structure				N	
(3) County Code	017	(4) Place code	00380	(105) Federal Lands Highways				0	
(8) Features Intersected	WATER FORT POND BROOK			(110) Designated National Network				N	
(7) Facility Carried	HWY RIVER ST			(20) Toll -	On free road			3	
(9) Location	0.9 MI. S.E. OF ST-27			(21) Maintain -	Town Agency			03	
(11) Kilometerpoint	0001.288			(22) Owner -	Town Agency			03	
(12) Base Highway Network	N			(37) Historical Significance	not eligible			N	
(13) LRS Inventory Route & Subroute	00000000000			Condition				Code	
(16) Latitude	42 DEG	27 MIN	24.73 SEC	(58) Deck				N	
(17) Longitude	71 DEG	26 MIN	14.01 SEC	(59) Superstructure				7	
(88) Border Bridge State Code	Share		%	(60) Substructure				7	
(89) Border Bridge Structure No. #				(61) Channel & Channel Protection				7	
Structure Type and Material				Load Rating and Posting				Code	
(43) Structure Type Main:	Steel	Code	311	(31) Design Load -	Other/Unknown			0	
Arch - Deck	Jointless bridge type: Not applicable			(63) Operating Rating Method -	Allowable Stress (AS)			2	
(44) Structure Type Appr:				(64) Operating Rating				31.8	
Other	Code	000		(65) Inventory Rating Method -	Allowable Stress (AS)			2	
(45) Number of spans in main unit	001			(66) Inventory Rating				22.7	
(46) Number of approach spans	0000			(70) Bridge Posting				4	
(107) Deck Structure Type -	Not applicable		Code N	(41) Structure -	Open			A	
(108) Wearing Surface / Protective System:				Appraisal				Code	
A) Type of wearing surface -	Not applicable=no deck		Code N	(67) Structural Evaluation				8	
B) Type of membrane -	Not applicable=no deck		Code N	(68) Deck Geometry				2	
C) Type of deck protection -	Not applicable=no deck		Code N	(69) Underclearances, vert. and horiz.				N	
Age and Service				(71) Waterway adequacy				7	
(27) Year Built	1937			(72) Approach Roadway Alignment				7	
(108) Year Reconstructed	0000			(36) Traffic Safety Features			0 0 1 1		
(42) Type of Service: On -	Highway			(113) Scour Critical Bridges				8	
Under -	Waterway		Code 15	Inspections					
(28) Lanes: On Structure	02	Under structure	00	(90) Inspection Date	12/05/05	(91) Frequency	24 MO		
(29) Average Daily Traffic	002000			(92) Critical Feature Inspection:		(93) CFI DATE			
(30) Year of ADT	2005	(108) Truck ADT	02 %	(A) Fracture Critical Detail	N 00	MO A)	00/00/00		
(19) Bypass, detour length	003 KM			(B) Underwater Inspection	N 00	MO B)	07/01/85		
Geometric Data				(C) Other Special Inspection	N 00	MO C)	00/00/00		
(48) Length of maximum span	0007.0 M			(*) Other Inspection ()	N 00	MO *)	00/00/00		
(49) Structure Length	00015.8 M			(*) Closed Bridge	N 00	MO *)	00/00/00		
(50) Curb or sidewalk:	Left	00.0 M	Right	00.0 M	(*) UW Special Inspection	N 00	MO *)	00/00/00	
(51) Bridge Roadway Width Curb to Curb	006.2 M			(*) Damage Inspection		MO *)	00/00/00		
(52) Deck Width Out to Out	007.6 M			Rating Loads					
(32) Approach Roadway Width (w/shoulders)	005.8 M			Report Date	12/01/01	H20	Type 3	Type 3S2	Type HS
(33) Bridge Median -	No median		Code 0	Operating	26.0	32.0	50.0	0.0	
(34) Skew	30 DEG	(35) Structure Flared	N	Inventory	20.0	23.0	36.0	0.0	
(10) Inventory Route MIN Vert Clear	99.99 M			Field Posting					
(47) Inventory Route Total Horiz Clear	06.2 M			Status	LEGAL	Posting Date	11/03/82		
(53) Min Vert Clear Over Bridge Rdwy	99.99 M			Actual	2 Axle	3 Axle	5 Axle		
(54) Min Vert Underclear ref	N		00.0 M	Recommended					
(55) Min Lat Underclear RT ref	N		00.0 M	Missing Signs	N				
(56) Min Lat Underclear LT	00.0 M			Misc.					
Navigation Data				Bridge Name					
(3) Navigation Control -	No navigation control on waterway			N	Anti-missile fence	N	Acrow Panel	N	Jointless Bridge
(4) Navigation Vertical Clearance	Code 0			Freeze/Thaw	N: Not Applicable				
(39) Navigation Vertical Clearance	000.0 M			Accessibility (Needed/Used)					
(118) Vert.-lift Bridge Nev Min Vert Clear	M			N / N	Liftbucket	N / N	Rigging	Inspection	
(40) Navigation Horizontal Clearance	0000.0 M			N / N	Ladder	N / N	Staging	Hours: 004	
				N / N	Boat	N / N	Traffic Control		
				Y / Y	Wader	N / N	RR Flaggerson		
				N / N	Inspector 50	N / N	Police		

MASSACHUSETTS HIGHWAY DEPARTMENT
STRUCTURES INSPECTION FIELD REPORT
CULVERT INSPECTION

2-DIST **03** B.I.N. **23Y**

BR. DEPT. NO.
A-02-009

CITY/TOWN ACTON		8-STRUCTURE NO. A02009-23Y-MUN-NBI		11-Kilo. POINT 000.354	41-STATUS A:OPEN	90-ROUTINE INSP. DATE DEC 5, 2005
07-FACILITY CARRIED HWY BROOK ST		MEMORIAL NAME/LOCAL NAME		27-YR BUILT 1938	106-YR REBUILT 0000	YR REHABD (NON 106) 0000
06-FEATURES INTERSECTED WATER NASHOBA BROOK		26-FUNCTIONAL CLASS Urban Collector		DIST. BRIDGE INSPECTION ENGINEER L. A. Gauthier		
43-STRUCTURE TYPE Steel Arch - Deck		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER J. Read		PROJ MOR Trasystems
107-DECK TYPE Not applicable		WEATHER Cloudy	TEMP. (air) -5°C	TEAM MEMBERS T. TAYLOR		

TYPE OF CULVERT:		BARRELS: (In Meters)	
SHAPE: BARREL		SIZE: 3.30mx2.20m	NUMBER: 2
MATERIAL: CORRUGATED STEEL		DEPTH OF COVER (To the nearest tenth of a meter)	
COATING: ASPHALTIC		0.6	0.6
		CURB REVEAL (In millimeters)	
		75	75

ITEM 62 CULVERT & RETAINING WALLS **6** 162 (Dive Report): **6** 162 (This Report): **7**

1. Roof	N	7	-	7. Protective Coating	7	7	-	13. Member Alignment	N	7	-	UNDERMINING (Y/N) # YES please explain N
2. Floor	7	7	-	8. Embankment	7	7	-	14. Deformation	8	7	-	
3. Walls	N	7	-	9. Wearing Surface	N	7	-	15. Scour	7	7	-	LOAD VIBRATION: <i>Please explain</i> None (<input checked="" type="checkbox"/>) Minor (<input type="checkbox"/>) Moderate (<input type="checkbox"/>) Severe (<input type="checkbox"/>)
4. Headwall	6	6	M-P	10. Railing	N	6	M-P	16. Settlement	7	7	-	
5. Wingwall	N	7	-	11. Sidewalks	N	6	M-P	17.				
6. Pipe	7	7	-	12. Utilities	N	N	-	18.				

ITEM 61 CHANNEL & CHANNEL PROTECTION **7** STREAM FLOW VELOCITY: Tidal () High () Moderate () Low ()

1. Channel Scour	7	7	-	5. Utilities	N	N	-	ITEM 61 (Dive Report): 7
2. Embankment Erosion	7	7	-	6. Rip-Rap/Slope Protection	7	N	-	
3. Debris	7	7	-	7. Aggradation	8	7	-	93b- U/W INSP DATE: 06/11/2004
4. Vegetation	7	7	-					

APPROACH CONDITION

a. Appr. pavement condition	7	-
b. Appr. Roadway Settlement	7	-
c. Appr. Sidewalk Settlement	N	-
d.		

WEIGHT POSTING

Actual Posting: **Not Applicable** H **3** **383** **Single**

Recommended Posting	N	N	N	N
Waived Date:	00/00/00	EJOMT Date:	12/17/1987	

Signs in Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility

At bridge		Advance	
E	W	E	W
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

ITEM 36 TRAFFIC SAFETY **ACCESSIBILITY** (Y/N/P):

A. Bridge Railing	0	6	M-P	Ladder	N	N	Other:		
B. Transitions	0	0	-	Boat	N	N		N	N
C. Approach Guardrail	1	7	-	Waders	Y	Y			
D. Approach Guardrail Ends	1	7	-						

TOTAL HOURS: **4**

PLANS (Y/N): **N**

(V.C.R.) (Y/N): **N**

TAPE#:

RATING

Request for Rating or Rerating (Y/N) **N** If YES please give priority: HIGH () MEDIUM () LOW ()

Rating Report (Y/N) **Y**

Date: **12/01/1987**

REASON:

R1a.Cul.(1)7-99

CITY/TOWN ACTON	B.I.N. 23Y	BR. DEPT. NO. A-02-009	8.-STRUCTURE NO. A02009-23Y-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS, PHOTOS & SKETCHES

BRIDGE ORIENTATION

Brook Street travels east and west over the Nashoba Brook which flows from north to south. The culvert barrels are numbered from west to east.

GENERAL REMARKS

There was a 1 in. snowfall on the night before the inspection which obscured the condition of the top of capstone and the sidewalk. Spot areas were cleaned off and inspected and based on these small areas the condition ratings from the previous report were continued to this report.

ITEM 62 - CULVERT

Item 62.4 - Headwall

The north headwall has two areas where the mortar between the masonry blocks is missing. The first area is located at 10:00 o'clock facing south on culvert 1 and measures 26 in. wide and 26 in. tall. The second is at 2:00 o'clock facing south on culvert 2 and measures 24 in. wide and 40 in. tall. The voids in these two areas were up to 1 ft. deep. (See Photo 3.) There is a hairline to narrow crack in the mortar joints between the stones located in the center between the culverts extending vertically from the cap stone to the first area mentioned above. There is an area with efflorescence staining extending from the west headwall end to above the center of culvert 1 from the street level down.

The south headwall has an area of masonry blocks with missing mortar located at 2:30 o'clock facing north on culvert 1. The voids in this area were measured to be up to 9 in. deep. There is another area of missing mortar between the masonry blocks located at 2:30 o'clock facing south on culvert 2. The voids in this area

CONDITION RATING GUIDE

CODE	CONDITION	DEFECTS
N	NOT APPLICABLE	Use if structure is not a culvert.
G 9	EXCELLENT	No deficiencies.
G 8	VERY GOOD	No noticeable or noteworthy differences which affect the condition of the culvert. Insignificant scrape marks caused by drift.
G 7	GOOD	Shrinkage cracks, light scaling, and insignificant spalling, which does not expose reinforcing steel. Insignificant damage caused by drift with not misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwalls, or pipes. Metal culverts have a smooth symmetrical curvature with superficial corrosion and no pitting.
F 6	SATISFACTORY	Deterioration or initial disintegration, minor chloride contamination, cracking with some leaching, or spalls on concrete or masonry walls and slabs. Local minor scouring at curtain walls, wingwalls, or pipes. Metal culverts have a smooth curvature, non-symmetrical shape, significant corrosion or moderate pitting.
F 5	FAIR	Moderate to major deterioration, or disintegration, extensive cracking and leaching, or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting.
P 4	POOR	Large spalls, heavy scaling, wide cracks, considerable efflorescence, or opened construction joints permitting loss of backfill. Considerable settlement or misalignment. Considerable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection throughout, extensive corrosion or deep pitting.
P 3	SERIOUS	Any condition described in Code 4 but which is excessive in scope. Severe movement or differential settlement of the segments, or loss of fill. Holes may exist in walls or slabs. Integral wingwalls, nearly severed from culvert. Severe scour or erosion at curtain walls, wingwalls, or pipes. Metal culverts have extreme distortion and deflection in one section, extensive corrosion, or deep pitting with scattered perforations.
C 2	CRITICAL	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C 1	"IMMINENT" FAILURE	Bridge closed. Corrective action may put back in light service.
0	FAILED	Bridge closed. Replacement necessary.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - (Examples include but are not limited to: Spalled concrete, minor to moderate corrosion to steel culverts, minor settlement or misalignment, minor scouring, minor damage to guardrail, etc.)

S= Severe/Major Deficiency - (Examples include but are not limited to: Large spalls, wide cracks, moderate to major deterioration in concrete, considerable settlement, considerable scouring or undermining, extensive corrosion and deflection in steel culverts, etc.)

C-S= Critical Deficiency - A deficiency in a structural component or element of a bridge that poses an extreme hazard or unsafe condition to the public. (Follow-up Critical Deficiency Report must be submitted separately)

URGENCY OF REPAIR:

I = Immediate - (Inspector(s) stay at the bridge until the District Maintenance crew or the responsible Agency crew (if not a State bridge) show up and corrective action is taken.)

A = ASAP - (Action will be taken by the District Maintenance Engineer or the Responsible Agency (if not a State owned bridge) upon receipt of the Inspection Report.)

P = Prioritize - (shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available.)

CITY/TOWN ACTON	B.I.N. 23Y	BR. DEPT. NO. A-02-009	8-STRUCTURE NO. A02009-23Y-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	--	---------------------------------------

REMARKS

Item 62.4 - Headwall (Cont'd)

were measured to be up to 30 in. deep. There are areas of hairline surface efflorescence in the mortar joints below the street surface in the south headwall primarily on the east side of culvert 2. There is a wide crack in the mortar joints located above culvert 1 and extending vertically from the cap stone to the keystone area. (See Photo 4.)

Item 62.6 - Pipe

The asphalt coating is cracked and the steel is rusting in a few spot locations above the waterline and there is rusting at the water level. There are spot locations of delaminating rust in both culverts at the ends just above the waterline.

Item 62.7 - Protective Coating

See Item 62.6 Pipe.

Item 62.9 - Wearing Surface

The wearing surface has moderate transverse and longitudinal wide cracking primarily in the eastbound travel lane.

Item 62.10 - Railing

The north and south bridge rails are made up of random laid up stone mortar with a stone cap. The mortar condition is good. Both have vertical and horizontal cracks in the mortar joints. The cracks are typically 1/8 to 1/4 in. in width. (See Photo 1.) The south bridge rail has a 1 in. wide crack located 16 ft. east of the west end. (See Photo 2.) No through cracks in stones were observed adjacent to or part of the vertical or horizontal cracks. The cap stone in each quadrant is losing mortar at the ends of the headwalls. Some of the cap stone joints are open.

TRAFFIC SAFETY

Item 36b - Transitions

There are no transitions.

Photo Log

- Photo 1 : Northeast bridge rail.
- Photo 2 : South bridge rail center span.
- Photo 3 : North headwall.
- Photo 4 : South end of culvert 1.

CITY/TOWN ACTON	B.I.N. 23Y	BR. DEPT. NO. A-02-009	8.-STRUCTURE NO. A02009-23Y-MUN-NBI	INSPECTION DATE DEC 5, 2005
---------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS



Photo 1: Northeast bridge rail.



Photo 2: South bridge rail center span.

CITY/TOWN
ACTON

B.I.N.
23Y

BR. DEPT. NO.
A-02-009

8.-STRUCTURE NO.
A02009-23Y-MUN-NBI

INSPECTION DATE
DEC 5, 2005

PHOTOS



Photo 3: North headwall.




Photo 4: South end of culvert 1.

MASSACHUSETTS HIGHWAY DEPARTMENT
UNDERWATER OPERATIONS TEAM
ROUTINE UNDERWATER INSPECTION REPORT

2-DIST
03

B.I.N.
23Y

BR. DEPT. NO.
A-02-009

CITY/TOWN ACTON		8-STRUCTURE NO. A02009-23Y-MUN-NBI		LEVEL OF INSPECTION II	93B-DATE INSPECTED APR 25, 2007
07-FACILITY CARRIED HWY BROOK ST		ACCESS TO BRIDGE EMBANKMENT	UNDERWATER OPERATIONS ENGINEER JOHN B. DESMOND		
06-FEATURES INTERSECTED WATER NASHOBA BROOK		DEPTH 1.3 m	VISIBILITY 1 m	TEAM LEADER (DIVE MASTER) SHARON A. BEGLEY	Report submitted by:
BOTTOM CONDITION GRAVEL		CURRENT MODERATE	TEAM MEMBERS E. P. TERNSKY		

ITEM 60	N	DEF	ITEM 61	7	DEF	ITEM 62	6	DEF
SUBSTRUCTURE			CHANNEL & CHANNEL PROTECTION			CULVERTS		
1. Abutments	N	-	1. Channel Scour	7	-	1. Roof	N	-
a. Pedestals	N	-	2. Embankment Erosion	7	-	2. Floor	7	-
b. Bridge Seats	N	-	3. Debris	7	-	3. Walls	N	-
c. Backwalls	N	-	4. Vegetation	7	-	4. Headwall	6	-
d. Breastwalls	N	-	5. Utilities	N	-	5. Wingwall	N	-
e. Wingwalls	N	-	6. Rip-Rap/Slope Protection	H	-	6. Pipe	7	-
f. Slope Paving/Rip-Rap	N	-	7. Aggradation	8	-	7. Protective Coating	7	-
g. Pointing	N	-	8. Fender System	N	-	8. Embankment	7	-
h. Footings	N	-	a. Piles	N	-	9. Wearing Surface	N	-
i. Piles	N	-	b. Diagonal Bracing	N	-	10. Railing	N	-
j. Scour	N	-	c. Horizontal Bracing	N	-	11. Sidewalks	N	-
k. Settlement	N	-	d. Weals	N	-	12. Utilities	N	-
l.	N	-	e. Fasteners	N	-	13. Member Alignment	N	-
2. Piers or Bents	N	-	f. Ladders	N	-	14. Deformation	8	-
a. Pedestals	N	-	g.	N	-	15. Scour	7	-
b. Caps	N	-	ITEM 50 SUPERSTRUCTURE			16. Settlement	7	-
c. Columns	N	-		N	-	17.	N	-
d. Stems/Webs/Pierwalls	N	-		N	-	18.	N	-
e. Pointing	N	-		N	-	UNDERMINING (Y/N)		
f. Footing	N	-						
g. Piles	N	-						
h. Scour	N	-						
i. Settlement	N	-						
j.	N	-						
k.	N	-						
3. Pile Bents	N	-						
a. Pile Caps	N	-						
b. Piles	N	-						
c. Diagonal Bracing	N	-						
d. Horizontal Bracing	N	-						
e. Fasteners	N	-						
UNDERMINING (Y/N)								

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

- M= Minor Deficiency-** Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor scouring, etc.
- S= Severe/Major Deficiency-** Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroding rebars, Deteriorated timber piles, Considerable settlement, Considerable scouring or undermining, etc.
- C-S= Critical Structural Deficiency-** A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.
- C-H= Critical Hazard Deficiency-** A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Any part of piles or fender system which are projecting outward and may become a safety hazard for the navigational traffic, etc.

URGENCY OF REPAIR:

- I=Immediate-** [Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her.]
- A=ASAP-** [Action/Repair should be initiated by District Maintenance Engineer or the responsible party (if not a State owned bridge) upon receipt of the Inspection Report.]
- P=Prioritize-** [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available.]

X=UNKNOWN

N=NOT APPLICABLE

H=HIDDEN/INACCESSIBLE

R=REMOVED

CITY/TOWN ACTON	B.I.N. 23Y	BR. DEPT. NO. A-02-009	S.-STRUCTURE NO. A02009-23Y-MUN-NBI	INSPECTION DATE APR 25, 2007
---------------------------	----------------------	----------------------------------	---	--

REMARKS

GENERAL REMARKS

- 1) Orientation - Abutments are labeled left and right when facing downstream.
- 2) Sta 10+00 is at the upstream end.
- 3) This structure is a double barrel ACCM culvert.

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.6 - Rip-Rap/Slope Protection

There is a small retaining wall located at upstream right with several voids from missing stones.

ITEM 62 - CULVERT

Item 62.2 - Floor

Floors consist of two layers, one each of concrete and bituminous and were mostly visible with small amounts of gravel covering.

Item 62.4 - Headwall

Headwall is dry laid below waterline with random missing chinking stones and small voids. See sketch.

Item 62.6 - Pipe

Twin ACCM pipes are in generally good condition with several small areas of minor corrosion where coating has deteriorated away .

Item 62.7 - Protective Coating

There are several small areas where coating has deteriorated away exposing metal pipes.

Item 62.15 - Scour

The river bed covers the invert of the pipe ends resulting in no exposure. There are several voids between pipes and walls at each end. See sketch for locations and dimensions.


Sketch / Chart Log

Sketch 1 : PLAN VIEW

Chart 1 : SCOUR MONITORING

CITY/TOWN ACTON	B.I.N. 23Y	BR. DEPT. NO. A-02-009	8.-STRUCTURE NO. A02009-23Y-MUN-NBI	INSPECTION DATE APR 25, 2007
---------------------------	----------------------	----------------------------------	---	--

SKETCHES



Sketch 1: PLAN VIEW

CITY/TOWN ACTON	B.I.N. 23Y	BR. DEPT. NO. A-02-009	8.-STRUCTURE NO. A02009-23Y-MUN-NBI	INSPECTION DATE APR 25, 2007
---------------------------	----------------------	----------------------------------	---	--

CHARTS

SCOUR MONITORING CHART

OFFSETS	6/22/95	7/28/98	7/5/01	6/11/04	4/25/07	
UPSTREAM LEFT CENTER OF SPAN	2.0	2.0	2.0	2.1	2.1	
UPSTREAM RIGHT CENTER OF SPAN	1.8	2.0	2.0	1.9	1.9	
DOWNSTREAM RIGHT CENTER OF SPAN	2.0	1.8				
DOWNSTREAM LEFT CENTER OF SPAN	1.2	1.5				
Y	4.5	4.4	2.3	3.4	2.8	
CORRECTION	-	-0.1	-2.2	-1.1	-1.7	

Notes

1. All soundings and measurements in english.
2. Water control shot (Y) = Waterline to apex of downstream right pipe.
3. For comparison all soundings are adjusted to 1995 water level.
4. Station 1+00 is located at the upstream end.

Chart 1: SCOUR MONITORING

MASSACHUSETTS HIGHWAY DEPARTMENT
STRUCTURES INSPECTION FIELD REPORT
CULVERT INSPECTION

2-DIST
03

B.I.N.
258

BR. DEPT. NO.
A-02-020

CITY/TOWN ACTON		8-STRUCTURE NO. A02020-258-MUN-NBI		11-Kilo. POINT 001.046	41-STATUS A:OPEN	90-ROUTINE INSP. DATE JAN 6, 2006
07-FACILITY CARRIED HWY RIVER ST		MEMORIAL NAME/LOCAL NAME		27-YR BUILT 1981	106-YR REBUILT 0000	YR REHABD (NON 106) 0000
06-FEATURES INTERSECTED WATER FORT POND BROOK		26-FUNCTIONAL CLASS Urban Local		DIST. BRIDGE INSPECTION ENGINEER L. A. Gauthier		
43-STRUCTURE TYPE Steel Culvert		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER R. C. Angell		
107-DECK TYPE Not applicable		WEATHER Cloudy	TEMP. (air) 1°C	TEAM MEMBERS L. A. GAUTHIER		

TYPE OF CULVERT:		BARRELS: (In Meters)	
SHAPE: ROUND		SIZE: 3.00mx3.05m	NUMBER: 2
MATERIAL: CORRUGATED STEEL		DEPTH OF COVER (To the nearest tenth of a meter)	
COATING: ASPHALTIC		0.6	0.6
		CURB REVEAL (In millimeters)	
		N	N

ITEM 62 CULVERT & RETAINING WALLS				7	162 (Dive Report): N	162 (This Report): 7						
1. Roof	N	N	-	7. Protective Coating	N	8	M-P	13. Member Alignment	N	8	-	UNDERMINING (Y/N) IF YES please explain N
2. Floor	N	N	-	8. Embankment	N	7	-	14. Deformation	N	8	-	
3. Walls	N	N	-	9. Wearing Surface	N	8	-	15. Scour	N	6	S-P	COLLISION DAMAGE: <u>Please explain</u> None (X) Minor () Moderate () Severe ()
4. Headwall	N	7	-	10. Railing	N	8	-	16. Settlement	N	7	-	
5. Wingwall	N	7	-	11. Sidewalks	N	N	-	17.				LOAD VIBRATION: <u>Please explain</u> None (X) Minor () Moderate () Severe ()
6. Pipe	N	7	M-P	12. Utilities	N	N	-	18.				

ITEM 61 CHANNEL & CHANNEL PROTECTION				7	STREAM FLOW VELOCITY: Tidal () High () Moderate (X) Low ()	APPROACH CONDITION				
1. Channel Scour	N	6	S-P	5. Utilities	N	N	-	a. Appr. pavement condition	7	-
2. Embankment Erosion	N	7	-	6. Rip-Rap/Slope Protector	N	7	-	b. Appr. Roadway Settlement	8	-
3. Debris	N	5	M-P	7. Aggradation	N	7	M-P	c. Appr. Sidewalk Settlement	N	-
4. Vegetation	N	7	-					d.		
				ITEM 61 (Dive Report): N		93b- U/W INSP DATE: 00/00/00				
				ITEM 61 (This Report): 7						

WEIGHT POSTING		Actual Posting				Signs In Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility			
Not Applicable <input checked="" type="checkbox"/>		H	S	352	Single	E	W	E	W
		N	N	N	N				
		N	N	N	N				
		Waived Date: 00/00/00	EJDMT Date: 00/00/00						

ITEM 35b TRAFFIC SAFETY				ACCESSIBILITY (Y/N/P):				TOTAL HOURS	
A. Bridge Railing	1	7	-	Ladder	N	N	Other:	8	
B. Transitions	1	7	-	Boat	N	N		PLANS (Y/N):	
C. Approach Guardrail	1	7	-	Waders	Y	Y		Y	
D. Approach Guardrail Ends	0	7	S-P					(V.C.R.) (Y/N):	
								N	
								TAPES:	

RATING		Request for Rating or Rerating (Y/N) Y		If YES please give priority: HIGH () MEDIUM () LOW (X)	
Rating Report (Y/N)	N	REASON: Based on design.			
Date:	00/00/00				

X=UNKNOWN N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE R=REMOVED

CITY/TOWN ACTON	B.I.N. 258	BR. DEPT. NO. A-02-020	8-STRUCTURE NO. A02020-258-MUN-NBI	INSPECTION DATE JAN 6, 2006
---------------------------	----------------------	----------------------------------	--	---------------------------------------

REMARKS, PHOTOS & SKETCHES

BRIDGE ORIENTATION

The approaches are W to E and the elevations are S to N. This is a two span pipe culvert with the barrels numbered from W to E. The brook flows from N to S.

ITEM 62 - CULVERT

Item 62.6 - Pipe

There are three small holes in the top of the W barrel near the S end, and two small holes in the top of the E barrel near the S end. These holes are a result of the vertical guardrail posts driven into the ground, and through the barrels. All of the holes are approx. 1-1/2 in. in diameter and are blocked with earth and show minor weeping. See photo #1. There are some nuts and bolts missing on the seams throughout both barrels, that were never installed.

Item 62.7 - Protective Coating

Asphaltic coating is wearing off on the bottom of both barrels and exposing the steel shell and resulting in some minor surface rusting.

Item 62.15 - Scour

Re: Item 61.1.

CONDITION RATING GUIDE

CODE	CONDITION	DEFECTS
N	NOT APPLICABLE	Use if structure is not a culvert.
G 9	EXCELLENT	No deficiencies.
G 8	VERY GOOD	No noticeable or noteworthy differences which affect the condition of the culvert. Insignificant scrape marks caused by drift.
G 7	GOOD	Shrinkage cracks, light scaling, and insignificant spalling, which does not expose reinforcing steel. Insignificant damage caused by drift with not misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwalls, or pipes. Metal culverts have a smooth, symmetrical curvature with superficial corrosion and no pitting.
F 6	SATISFACTORY	Deterioration or initial disintegration, minor chloride contamination, cracking with some leaching, or spalls on concrete or masonry walls and slabs. Local minor scouring at curtain walls, wingwalls, or pipes. Metal culverts have a smooth curvature, non-symmetrical shape, significant corrosion or moderate pitting.
F 5	FAIR	Moderate to major deterioration, or disintegration, extensive cracking and leaching, or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting.
P 4	POOR	Large spalls, heavy scaling, wide cracks, considerable efflorescence, or opened construction joints permitting loss of backfill. Considerable settlement or misalignment. Considerable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection throughout, extensive corrosion or deep pitting.
P 3	SERIOUS	Any condition described in Code 4 but which is excessive in scope. Severe movement or differential settlement of the segments, or loss of fill. Holes may exist in walls or slabs. Integral wingwalls, nearly severed from culvert. Severe scour or erosion at curtain walls, wingwalls, or pipes. Metal culverts have extreme distortion and deflection in one section, extensive corrosion, or deep pitting with scattered perforations.
C 2	CRITICAL	Advance deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C 1	"IMMINENT" FAILURE	Bridge closed. Corrective action may put back in light service.
0	FAILED	Bridge closed. Replacement necessary.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - (Examples include but are not limited to: Spalled concrete, minor to moderate corrosion to steel culverts, minor settlement or misalignment, minor scouring, minor damage to guardrail, etc.)

S= Severe/Major Deficiency - (Examples include but are not limited to: Large spalls, wide cracks, moderate to major deterioration in concrete, considerable settlement, considerable scouring or undermining, extensive corrosion and deflection in steel culverts, etc.)

C-S= Critical Deficiency - A deficiency in a structural component or element of a bridge that poses an extreme hazard or unsafe condition to the public. (Follow-up Critical Deficiency Report must be submitted separately)

URGENCY OF REPAIR:

I = Immediate - (Inspector(s) stay at the bridge until the District Maintenance crew or the responsible Agency crew (if not a State bridge) show up and corrective action is taken.)

A = ASAP - (Action will be taken by the District Maintenance Engineer or the Responsible Agency (if not a State owned bridge) upon receipt of the Inspection Report.)

P = Prioritize - (Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available.)

CITY/TOWN ACTON	B.I.N. 258	BR. DEPT. NO. A-02-020	8.-STRUCTURE NO. A02020-258-MUN-NBI	INSPECTION DATE JAN 6, 2006
---------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.1 - Channel Scour

The minor piping behind both barrels of the culvert at the N end, noted on the previous inspection, could not be detected due to the high water level.

Item 61.3 - Debris

There is a moderate build up of debris (tree limbs, branches, & leaves) to upstream side of W barrel. See photo #2. There is a minor build up of debris (tree limbs & branches) to downstream side of W barrel. This debris is causing little effect on stream flow.

Item 61.7 - Aggradation

There is a minor build up of alluvial material (sand, gravel, & small stones) throughout both barrels. This debris is not restricting the flow.

TRAFFIC SAFETY

Item 36d - Approach Guardrail Ends

The SW, NW, & NE terminal ends are boxing glove ends that are not sufficiently turned from traffic.

Photo Log

Photo 1 : Two small holes to S barrel, typical of three small holes in N barrel.

Photo 2 : Debris at upstream side of W culvert barrel.

CITY/TOWN
ACTON

B.I.N.
258

BR. DEPT. NO.
A-02-020

8.-STRUCTURE NO.
A02020-258-MUN-NBI

INSPECTION DATE
JAN 6, 2006

PHOTOS



Photo 1: Two small holes to S barrel, typical of three small holes in N barrel.



Photo 2: Debris at upstream side of W culvert barrel.

Report Date: October 23, 2007

State Information				Classification				Code				
BDEPT# A02020				Agency Br.No.				(112) NBIS Bridge Length				Y
Town Acton				AASHTO# 098.9				(104) Highway System				N
B.I.N# 258				FHWA Select List# N				(28) Functional Class - Urban Local				19
Structure Number				A02020258MUNNBI				(100) Defense Highway				0
(5) Inventory Route				151000000				(101) Parallel Structure				N
(2) State Highway Department District				03				(102) Direction of Traffic - 2-way traffic				2
(3) County Code 017				(4) Place code 00380				(103) Temporary Structure				N
(6) Features Intersected				WATER FORT POND BROOK				(105) Federal Lands Highways				0
(7) Facility Carried				HWY RIVER ST				(110) Designated National Network				N
(9) Location				.8 MI. E OF ST. 27				(20) Toll - On free road				3
(11) Kilometerpoint				0001.048				(21) Maintain - Town Agency				03
(12) Base Highway Network				N				(22) Owner - Town Agency				03
(13) LRS Inventory Route & Subroute				000000000000				(37) Historical Significance - undetermined				
(16) Latitude				42 DEG 27 MIN 30.12 SEC				Condition				Code
(17) Longitude				71 DEG 28 MIN 27.00 SEC				(58) Deck				N
(98) Border Bridge State Code				Share %				(59) Superstructure				N
(99) Border Bridge Structure No. #								(60) Substructure				N
Structure Type and Material								(61) Channel & Channel Protection				7
(43) Structure Type Main: Steel				Code 319				(62) Culverts				7
Culvert				Jointless bridge type: Not applicable				Load Rating and Posting				Code
(44) Structure Type Appr: Other				Code 000				(31) Design Load - H 20=M 18				4
(45) Number of spans in main unit				002				(63) Operating Rating Method - No rating analysis performed				5
(46) Number of approach spans				0000				(64) Operating Rating				44.1
(107) Deck Structure Type - Not applicable				Code N				(65) Inventory Rating Method - No rating analysis performed				5
(108) Wearing Surface / Protective System:								(66) Inventory Rating				32.4
A) Type of wearing surface - Not applicable=no deck				Code N				(70) Bridge Posting				5
B) Type of membrane - Not applicable=no deck				Code N				(41) Structure - Open				A
Type of deck protection - Not applicable=no deck				Code N				Appraisal				Code
Age and Service								(67) Structural Evaluation				7
(27) Year Built				1981				(68) Deck Geometry				5
(106) Year Reconstructed				0000				(69) Underclearances, vert. and horiz.				N
(42) Type of Service: On - Highway								(71) Waterway adequacy				8
Under - Waterway				Code 15				(72) Approach Roadway Alignment				7
(26) Lanes: On Structure 02				Under structure 00				(38) Traffic Safety Features				1 1 1 0
(29) Average Daily Traffic				000500				(113) Scour Critical Bridges				8
(30) Year of ADT 2006				(109) Truck ADT 08 %				Inspections				
(19) Bypass, detour length				003 KM				(90) Inspection Date 01/08/06				(91) Frequency 24 MO
Geometric Data								(92) Critical Feature Inspection:				(93) CFI DATE
(48) Length of maximum span				0003.0 M				(A) Fracture Critical Detail				N 00 MO A) 00/00/00
(49) Structure Length				00007.6 M				(B) Underwater Inspection				N 00 MO B) 07/01/85
(50) Curb or sidewalk: Left 00.0 M				Right 00.0 M				(C) Other Special Inspection				N 00 MO C) 00/00/00
(51) Bridge Roadway Width Curb to Curb				008.6 M				(*) Other Inspection ()				N 00 MO *) 00/00/00
(52) Deck Width Out to Out				015.2 M				(*) Closed Bridge				N 00 MO *) 00/00/00
(32) Approach Roadway Width (w/shoulders)				008.2 M				(*) UW Special Inspection				N 00 MO *) 00/00/00
(33) Bridge Median - No median				Code 0				(*) Damage Inspection				N 00 MO *) 00/00/00
(34) Skew 00 DEG				(35) Structure Flared N				Rating Loads				
(10) Inventory Route MIN Vert Clear				89.99 M				Report Date 00/00/00				H20 Type 3 Type 3S2 Type HS
(47) Inventory Route Total Horiz Clear				08.6 M				Operating				27.0 34.0 49.0 49.0
(53) Min Vert Clear Over Bridge Rdwy				99.99 M				Inventory				20.0 25.0 36.0 36.0
(54) Min Vert Underclear ref N				00.00 M				Field Posting				
(55) Min Lat Underclear RT ref N				00.0 M				Status DESIGN				Posting Date 01/01/61
(56) Min Lat Underclear LT				00.0 M				Actual				2 Axle 3 Axle 5 Axle
Navigation Data								Recommended				
(3) Navigation Control - No navigation control on waterway				Code 0				Missing Signs N				
(1) Navigation Protection				Code				Misc.				
(39) Navigation Vertical Clearance				000.0 M				Bridge Name				N Anti-missile fence N Acrow Panel N Jointless Bridge
(116) Vert-lift Bridge Nav Min Vert Clear				M				Freeze/Thaw N : Not Applicable				
(40) Navigation Horizontal Clearance				0000.0 M				Accessibility (Needed/Used)				
								N / N Liftbucket				N / N Rigging Inspection
								N / N Ladder				N / N Staging Hours: 008
								N / N Boat				N / N Traffic Control
								Y / Y Wader				N / N RR Flagperson
								N / N Inspector 50				N / N Police

MASSACHUSETTS HIGHWAY DEPARTMENT
STRUCTURES INSPECTION FIELD REPORT
CULVERT INSPECTION

2-DIST
03

B.I.N.
259

BR. DEPT. NO.
A-02-021

CITY/TOWN ACTON		8-STRUCTURE NO. A02021-259-MUN-NBI	11-Kilo. POINT 000.805	41-STATUS A:OPEN	90-ROUTINE INSP. DATE JAN 18, 2006	
07-FACILITY CARRIED HWY RIVER ST		MEMORIAL NAME/LOCAL NAME		27-YR BUILT 1981	106-YR REBUILT 0000	YR REHAB'D (NON 106) 0000
06-FEATURES INTERSECTED WATER FORT POND BROOK		26-FUNCTIONAL CLASS Urban Local		DIST. BRIDGE INSPECTION ENGINEER L. A. Gauthier		
43-STRUCTURE TYPE Steel Culvert		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER S. A. Begley		
107-DECK TYPE Not applicable		WEATHER Rain	TEMP. (air) 6°C	TEAM MEMBERS M. DYGON		

TYPE OF CULVERT:		BARRELS: (In Meters)	
SHAPE:	PIPE ARCH	SIZE:	2.70mx2.00m
MATERIAL:	CORRUGATED STEEL	NUMBER:	2
COATING:	ASPHALTIC	DEPTH OF COVER (To the nearest tenth of a meter)	
		N	S
		0.6	0.6
		CURB REVEAL (In millimeters)	
		N	N

ITEM 62 CULVERT & RETAINING WALLS				7	162 (Dive Report): N	162 (This Report): 7
Dive This Rpt.	DEF	Dive This Rpt.	DEF	Dive This Rpt.	DEF	
1. Roof	N 7 -	7. Protective Coating	N 5 M-P	13. Member Alignment	N 8 -	UNDERMINING (Y/N) If YES please explain N
2. Floor	N 6 M-P	8. Embankment	N 7 -	14. Deformation	N 7 -	
3. Walls	N 7 -	9. Wearing Surface	N 7 -	15. Scour	N 6 M-P	COLLISION DAMAGE: <i>Please explain</i> None (<input checked="" type="checkbox"/>) Minor (<input type="checkbox"/>) Moderate (<input type="checkbox"/>) Severe (<input type="checkbox"/>)
4. Headwall	N 6 M-P	10. Railing	N 7 -	16. Settlement	N 7 -	
5. Wingwall	N N -	11. Sidewalks	N N -	17. Channel Wall	N 5 M-P	LOAD VIBRATION: <i>Please explain</i> None (<input checked="" type="checkbox"/>) Minor (<input type="checkbox"/>) Moderate (<input type="checkbox"/>) Severe (<input type="checkbox"/>)
6. Pipe	N N -	12. Utilities	N N -	18.		

ITEM 61 CHANNEL & CHANNEL PROTECTION				7	STREAM FLOW VELOCITY: Tidal (<input type="checkbox"/>) High (<input checked="" type="checkbox"/>) Moderate (<input type="checkbox"/>) Low (<input type="checkbox"/>)	APPROACH CONDITION	
Dive This Rpt.	DEF	Dive This Rpt.	DEF	Dive This Rpt.	DEF		
1. Channel Scour	N 6 M-P	5. Utilities	N N -	ITEM 61 (Dive Report): N		a. Appr. pavement condition	7 -
2. Embankment Erosion	N 7 -	6. Rip-Rap/Slope Protection	N 7 -	ITEM 61 (This Report): 7		b. Appr. Roadway Settlement	7 -
3. Debris	N 5 M-P	7. Aggradation	N 7 -	93b- U/W INSP DATE: 00/00/00		c. Appr. Sidewalk Settlement	N -
4. Vegetation	N 7 -					d.	

WEIGHT POSTING		Actual Posting				Signs in Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility			
Not Applicable <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	H	3	352	Single	E	W	E	W
		N	N	N	N	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Recommended Posting		N	N	N	N				
Waived Date: 00/00/00		EJDMT Date: 00/00/00							

ITEM 56 TRAFFIC SAFETY				ACCESSIBILITY (Y/N/P):				TOTAL HOURS	
								8	
A. Bridge Railing	1	7	-	Ladder	N	N	Other:	PLANS (Y/N): Y	
B. Transitions	1	7	-	Boat	N	N		(V.C.R.) (Y/N): N	
C. Approach Guardrail	1	7	-	Waders	Y	Y		TAPES:	
D. Approach Guardrail Ends	1	5	M-P						

RATING		Request for Rating or Rerating (Y/N) Y		If YES please give priority: HIGH (<input type="checkbox"/>) MEDIUM (<input type="checkbox"/>) LOW (<input checked="" type="checkbox"/>)	
Rating Report (Y/N)	N	REASON: Based on Design			
Date:	00/00/00				

X=UNKNOWN N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE R=REMOVED

CITY/TOWN ACTON	B.I.N. 259	BR. DEPT. NO. A-02-021	8.-STRUCTURE NO. A02021-259-MUN-NBI	INSPECTION DATE JAN 18, 2006
---------------------------	----------------------	----------------------------------	---	--

REMARKS, PHOTOS & SKETCHES

BRIDGE ORIENTATION

The approaches are West and East and the elevations are South and North. This is a two barrel culvert with the barrels numbered from West to East. The brook flows from South to North.

ITEM 62 - CULVERT

Item 62.1 - Roof

There is a slight bow, approx. 2 in., in the West barrel. See photo 1.

Item 62.2 - Floor

The asphaltic coating is wearing away along both floors, up to the waterline causing surface rusting. See photo 2. 10% of the floor in barrel #1 is covered with gravel. 90% of the floor in barrel #2 is covered with gravel.

Item 62.4 - Headwall

The South headwall has minor cracking. There is a 2 1/2 ft. diameter x 2 ft. deep sinkhole in the fill behind the South guardrail above barrel #2, 2 ft. from the back of the headwall. See photo 3.

Item 62.7 - Protective Coating

See Item 62.2 for comments.

CONDITION RATING GUIDE

CODE	CONDITION	DEFECTS
N	NOT APPLICABLE	Use if structure is not a culvert.
G 9	EXCELLENT	No deficiencies.
G 8	VERY GOOD	No noticeable or noteworthy differences which affect the condition of the culvert. Insignificant scrape marks caused by drift.
G 7	GOOD	Shrinkage cracks, light scaling, and insignificant spalling, which does not expose reinforcing steel. Insignificant damage caused by drift with not misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwalls, or pipes. Metal culverts have a smooth, symmetrical curvature with superficial corrosion and no pitting.
F 6	SATISFACTORY	Deterioration or initial disintegration, minor chloride contamination, cracking with some leaching, or spalls on concrete or masonry walls and slabs. Local minor scouring at curtain walls, wingwalls, or pipes. Metal culverts have a smooth curvature, non-symmetrical shape, significant corrosion or moderate pitting.
F 5	FAIR	Moderate to major deterioration, or disintegration, extensive cracking and leaching, or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting.
P 4	POOR	Large spalls, heavy scaling, wide cracks, considerable efflorescence, or opened construction joints permitting loss of backfill. Considerable settlement or misalignment. Considerable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection throughout, extensive corrosion or deep pitting.
P 3	SERIOUS	Any condition described in Code 4 but which is excessive in scope. Severe movement or differential settlement of the segments, or loss of fill. Holes may exist in walls or slabs. Integral wingwalls, nearly severed from culvert. Severe scour or erosion at curtain walls, wingwalls, or pipes. Metal culverts have extreme distortion and deflection in one section, extensive corrosion, or deep pitting with scattered perforations.
C 2	CRITICAL	Advance deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or occur may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C 1	"IMMINENT" FAILURE	Bridge closed. Corrective action may put back in light service.
0	FAILED	Bridge closed. Replacement necessary.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - (Examples include but are not limited to: Spalled concrete, minor to moderate corrosion to steel culverts, minor settlement or misalignment, minor scouring, minor damage to guardrail, etc.)

S= Severe/Major Deficiency - (Examples include but are not limited to: Large spalls, wide cracks, moderate to major deterioration in concrete, considerable settlement, considerable scouring or undermining, extensive corrosion and deflection in steel culverts, etc.)

C-S= Critical Deficiency - A deficiency in a structural component or element of a bridge that poses an extreme hazard or unsafe condition to the public. (Follow-up Critical Deficiency Report must be submitted separately)

URGENCY OF REPAIR:

I = Immediate - (Inspector(s) stay at the bridge until the District Maintenance crew or the responsible Agency crew (if not a State bridge) show up and corrective action is taken.)

A = ASAP - (Action will be taken by the District Maintenance Engineer or the Responsible Agency (if not a State owned bridge) upon receipt of the Inspection Report.)

P = Prioritize - (shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available)

CITY/TOWN ACTON	B.I.N. 259	BR. DEPT. NO. A-02-021	8.-STRUCTURE NO. A02021-259-MUN-NBI	INSPECTION DATE JAN 18, 2006
---------------------------	----------------------	----------------------------------	---	--

REMARKS

Item 62.9 - Wearing Surface

There is a 4 ft. minor transverse crack midspan in the East bound lane.

Item 62.14 - Deformation

See Item 62.1.

Item 62.15 - Scour

See Item #61.1

Item 62.17 - Channel Wall

A 5 ft. high x 4 ft. 4 inches wide x 4 ft. deep section of the Southwest channel wall has collapsed. See photo 4.

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.1 - Channel Scour

The upstream end is channelized with mortared granite and field stone retaining walls. The steep grade of the channel approach increases the stream flow velocity slightly. There is minor channel scour just below the West barrel at the upstream opening. Taken from previous inspection report of 01-26-2004 due to debris across both barrels and extreme velocity condition.

Item 61.3 - Debris

There is debris upstream across both barrels. See photo 5.

Item 61.7 - Aggradation

See Item 62.2.

APPROACHES

Approaches a - Appr. pavement condition

There is a full width 1/4 inch wide transverse crack in the West approach.

TRAFFIC SAFETY

Item 36b - Transitions

The Northeast transition rail has minor collision damage.

Item 36c - Approach Guardrail

The Northeast approach rail has minor collision damage.

Item 36d - Approach Guardrail Ends

The Southeast terminal end end has moderate collision damage. See photo 6.

Photo Log

- Photo 1: Barrel #1 (West).
- Photo 2: Surface rusting to barrel. Typical.
- Photo 3: Sinkhole above barrel #2. South end.
- Photo 4: Collapse to the Southwest channel wall.
- Photo 5: Debris across both barrels at the upstream end.
- Photo 6: Collision damage to the Southeast terminal end.

CITY/TOWN ACTON	B.I.N. 259	BR. DEPT. NO. A-02-021	8.-STRUCTURE NO. A02021-259-MUN-NBI	INSPECTION DATE JAN 18, 2006
--------------------	---------------	---------------------------	--	---------------------------------

PHOTOS




Photo 1: Barrel #1 (West).



Photo 2: Surface rusting to barrel. Typical.

CITY/TOWN
ACTON

B.I.N.
259

BR. DEPT. NO.
A-02-021

8.-STRUCTURE NO.
A02021-259-MUN-NBI

INSPECTION DATE
JAN 18, 2006

PHOTOS



Photo 3: Sinkhole above barrel #2. South end.



Photo 4: Collapse to the Southwest channel wall.

CITY/TOWN ACTON	B.I.N. 259	BR. DEPT. NO. A-02-021	8.-STRUCTURE NO. A02021-259-MUN-NBI	INSPECTION DATE JAN 18, 2006
--------------------	---------------	---------------------------	--	---------------------------------

PHOTOS




Photo 5: Debris across both barrels at the upstream end.



Photo 6: Collision damage to the Southeast terminal end.

Report Date: October 23, 2007

State Information				Classification				Code
BDEPT#	A02021	Agency Br.No.		(112) NBIS Bridge Length				Y
Town	Action			(104) Highway System				N
B.I.N#	269	AASHTO#	097.4	(26) Functional Class -	Urban Local			19
		FHWA Select List#	N	(100) Defense Highway				0
Structure Number	A02021259MUNNBI			(101) Parallel Structure				N
(5) Inventory Route	151000000			(102) Direction of Traffic -	2-way traffic			2
(2) State Highway Department District	03			(103) Temporary Structure				N
(3) County Code	017	(4) Place code	00380	(105) Federal Lands Highways				0
(6) Features Intersected	WATER FORT POND BROOK			(110) Designated National Network				N
(7) Facility Carried	HWY RIVER ST			(20) Toll -	On free road			3
(9) Location	ACROSS FROM VANDERBELT ST			(21) Maintain -	Town Agency			03
(11) Kilometerpoint	0000.805			(22) Owner -	Town Agency			03
(12) Base Highway Network	N			(37) Historical Significance	undetermined			
(13) LRS Inventory Route & Subroute	000000000000			Condition				Code
(16) Latitude	42 DEG 27 MIN 33.58 SEC			(58) Deck				N
(17) Longitude	71 DEG 28 MIN 34.57 SEC			(59) Superstructure				N
(66) Border Bridge State Code		Share	%	(60) Substructure				N
(99) Border Bridge Structure No. #				(61) Channel & Channel Protection				7
				(62) Culverts				7
Structure Type and Material				Load Rating and Posting				Code
(43) Structure Type Main:	Steel	Code	319	(31) Design Load -	Other/Unknown			0
Culvert	Jointless bridge type:	Not applicable		(63) Operating Rating Method -	No rating analysis performed			5
(44) Structure Type Appr:		Code	000	(64) Operating Rating				44.1
Other				(65) Inventory Rating Method -	No rating analysis performed			5
(45) Number of spans in main unit			002	(66) Inventory Rating				32.4
(46) Number of approach spans			0000	(70) Bridge Posting				5
(107) Deck Structure Type -	Not applicable	Code	N	(41) Structure -	Open			A
(108) Wearing Surface / Protective System:				Appraisal				Code
A) Type of wearing surface -	Not applicable=no deck	Code	N	(67) Structural Evaluation				7
B) Type of membrane -	Not applicable=no deck	Code	N	(68) Deck Geometry				5
Type of deck protection -	Not applicable=no deck	Code	N	(69) Underclearances, vert. and horiz.				N
				(71) Waterway adequacy				6
Age and Service				(72) Approach Roadway Alignment				6
(27) Year Built			1981	(36) Traffic Safety Features		1	1	1
(106) Year Reconstructed			0000	(113) Scour Critical Bridges				8
(42) Type of Service: On -	Highway			Inspections				
Under -	Waterway	Code	15	(90) Inspection Date	01/18/06	(91) Frequency	24	MO
(28) Lanes: On Structure	02	Under structure	00	(92) Critical Feature Inspection:		(93) CFI DATE		
(29) Average Daily Traffic			000600	(A) Fracture Critical Detail	N 00	MO A)	00/00/00	
(30) Year of ADT	2002	(109) Truck ADT	15 %	(B) Underwater Inspection	N 00	MO B)	07/01/85	
(19) Bypass, detour length			003 KM	(C) Other Special Inspection	N 00	MO C)	00/00/00	
Geometric Data				(*) Other Inspection ()	N 00	MO *)	00/00/00	
(48) Length of maximum span			0002.7 M	(*) Closed Bridge	N 00	MO *)	00/00/00	
(49) Structure Length			00006.8 M	(*) UW Special Inspection	N 00	MO *)	00/00/00	
(50) Curb or sidewalk:	Left 00.0 M	Right	00.0 M	(*) Damage Inspection		MO *)	00/00/00	
(51) Bridge Roadway Width Curb to Curb			006.4 M	Rating Loads				
(52) Deck Width Out to Out			011.0 M	Report Date	00/00/00	H20	Type 3	Type 3S2
(32) Approach Roadway Width (w/shoulders)			005.2 M	Operating		27.0	34.0	49.0
(33) Bridge Median -	No median	Code	0	Inventory		20.0	25.0	36.0
(34) Skew	41 DEG	(35) Structure Flared	N	Field Posting				
(10) Inventory Route MIN Vert Clear			99.99 M	Status	DESIGN	Posting Date		01/01/81
(47) Inventory Route Total Horiz Clear			06.4 M		2 Axle	3 Axle	5 Axle	
(53) Min Vert Clear Over Bridge Rdwy			99.99 M	Actual				
(54) Min Vert Underclear ref	N		00.00 M	Recommended				
(55) Min Lat Underclear RT ref	N		00.0 M	Missing Signs	N			
(56) Min Lat Underclear LT			00.0 M	Misc.				
Navigation Data				Bridge Name				
(7) Navigation Control -	No navigation control on waterway	Code	0	N	Anti-missile fence	N	Acrow Panel	N
(8) Navigation Protection		Code	000.0 M	N	Jointless Bridge			
(39) Navigation Vertical Clearance			M	Freeze/Thaw				N : Not Applicable
(116) Vert-lift Bridge Nav Min Vert Clear			M	Accessibility (Needed/Used)				
(40) Navigation Horizontal Clearance			0000.0 M	N / N	Liftbucket	N / N	Rigging	Inspection
				N / N	Ladder	N / N	Staging	Hours: 008
				N / N	Boat	N / N	Traffic Control	
				Y / Y	Wader	N / N	RR Flagperson	
				N / N	Inspector 50	N / N	Police	

MASSACHUSETTS HIGHWAY DEPARTMENT
STRUCTURES INSPECTION FIELD REPORT
CULVERT INSPECTION

2-DIST
03

B.I.N.
25B

BR. DEPT. NO.
A-02-023

CITY/TOWN ACTON		8-STRUCTURE NO. A02023-25B-MUN-NBI	11-Kilo. POINT 000.386	41-STATUS A:OPEN	90-ROUTINE INSP. DATE JAN 6, 2006
07-FACILITY CARRIED HWY MARTIN ST		MEMORIAL NAME/LOCAL NAME		27-YR BUILT 1965	106-YR REBUILT 0000
06-FEATURES INTERSECTED WATER FORT POND BROOK		26-FUNCTIONAL CLASS Urban Local		DIST. BRIDGE INSPECTION ENGINEER L. A. Gauthier	
43-STRUCTURE TYPE Steel Culvert		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER R. C. Angell	
107-DECK TYPE Not applicable		WEATHER Cloudy	TEMP (air) 1°C	TEAM MEMBERS L. A. GAUTHIER	

TYPE OF CULVERT:		BARRELS: (In Meters)	
SHAPE: PIPE ARCH	MATERIAL: CORRUGATED STEEL	SIZE: 1.80mx2.70m	NUMBER: 2
COATING: ASPHALTIC	DEPTH OF COVER (To the nearest tenth of a meter)		E 0.3 W 0.6
		CURB REVEAL (In millimeters)	N N

ITEM 62 CULVERT & RETAINING WALLS 7 162 (Dive Report): **N** 162 (This Report): **7**

	Dive This	DEF		Dive This	DEF		Dive This	DEF			
	Rep.	Rpt.		Rep.	Rpt.		Rep.	Rpt.			
1. Roof	N	7	-	7. Protective Coating	N	8	M-P	13. Member Alignment	N	7	-
2. Floor	N	6	M-P	8. Embankment	N	7	-	14. Deformation	N	7	-
3. Walls	N	7	-	9. Wearing Surface	N	8	-	15. Scour	N	7	-
4. Headwall	N	7	M-P	10. Railing	N	8	-	16. Settlement	N	7	-
5. Wingwall	N	7	-	11. Sidewalks	N	8	-	17.			
6. Pipe	N	N	-	12. Utilities	N	N	-	18.			

UNDERMINING (Y/N) **IF YES please explain** **N**

COLLISION DAMAGE: **Please explain**
 None () Minor () Moderate () Severe ()

LOAD VIBRATION: **Please explain**
 None () Minor () Moderate () Severe ()

ITEM 61 CHANNEL & CHANNEL PROTECTION 7

	Dive This	DEF		Dive This	DEF		
	Rep.	Rpt.		Rep.	Rpt.		
1. Channel Scour	N	7	-	5. Utilities	N	H	-
2. Embankment Erosion	N	6	M-P	8. Rip-Rap/Slope Protection	N	7	-
3. Debris	N	7	-	7. Aggradation	N	7	-
4. Vegetation	N	7	-				

STREAM FLOW VELOCITY:
 Tidal () High () Moderate () Low ()

APPROACH CONDITION

	DEF
a. Appr. pavement condition	8 -
b. Appr. Roadway Settlement	8 -
c. Appr. Sidewalk Settlement	8 -
d.	

ITEM 61 (Dive Report): **N**
 ITEM 61 (This Report): **7**

93b-
 UW INSP DATE: **00/00/00**

WEIGHT POSTING

Not Applicable Actual Posting N N N N

Recommended Posting 17 23 36 N

Waived Date: **07/21/1982** EJDMT Date: **00/00/00**

Signs in Place (Y=Yes, N=No, NR=Not/Required)
 Legibility/Visibility

At bridge		Advance	
N	S	N	S
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

ITEM 36 TRAFFIC SAFETY

	36	COND	DEF
A. Bridge Railing	1	8	-
B. Transitions	1	8	-
C. Approach Guardrail	1	8	-
D. Approach Guardrail Ends	0	8	-

ACCESSIBILITY (Y/N/P):

	Needed	Used	Other:	Needed	Used
Ladder	N	N			
Boat	N	N		N	N
Waders	Y	Y			

TOTAL HOURS **8**

PLANS (Y/N): **Y**

(V.C.R.) (Y/N): **N**

TAPES: _____

RATING

Request for Rating or Rerating (Y/N) **N** IF YES please give priority:
 HIGH () MEDIUM () LOW ()

Rating Report (Y/N) **Y**

Date: **03/01/1982** REASON: _____

CITY/TOWN ACTON	B.I.N. 25B	BR. DEPT. NO. A-02-023	8.-STRUCTURE NO. A02023-25B-MUN-NBI	INSPECTION DATE JAN 6, 2006
---------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS, PHOTOS & SKETCHES

BRIDGE ORIENTATION

The approaches are S to N and the elevations are W to E. This a two span pipe arch with the barrels numbered from S to N. The brook flows from W to E.

ITEM 62 - CULVERT

Item 62.2 - Floor

The floors of both barrels show heavy surface rusting and minor to moderate corrosion throughout, from high waterline down. The asphaltic coating has worn off throughout most of both barrel floors. No photo taken due to high water.

Item 62.4 - Headwall

There is one granite headwall block missing at the waterline, at the upstream nose, between the two barrels.

Item 62.7 - Protective Coating

Re: Item 62.2.

Item 62.9 - Wearing Surface

The bit. conc. wearing surface is new since last inspection.

Item 62.10 - Railing

There is chain link fence behind "SS" type bridgerail at E side of culvert (sidewalk side). This fence acts as a pedestrian safety barricade. See photo #1.

CONDITION RATING GUIDE

CODE	CONDITION	DEFECTS
N	NOT APPLICABLE	Use if structure is not a culvert.
G 9	EXCELLENT	No deficiencies.
G 8	VERY GOOD	No noticeable or noteworthy differences which affect the condition of the culvert. Insignificant scrape marks caused by drift.
G 7	GOOD	Shrinkage cracks, light scaling, and insignificant spalling, which does not expose reinforcing steel. Insignificant damage caused by drift with not misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwalls, or pipes. Metal culverts have a smooth symmetrical curvature with superficial corrosion and no pitting.
F 6	SATISFACTORY	Deterioration or initial disintegration, minor chloride contamination, cracking with some leaching, or spalls on concrete or masonry walls and slabs. Local minor scouring at curtain walls, wingwalls, or pipes. Metal culverts have a smooth curvature, non-symmetrical shape, significant corrosion or moderate pitting.
F 5	FAIR	Moderate to major deterioration, or disintegration, extensive cracking and leaching, or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting.
P 4	POOR	Large spalls, heavy scaling, wide cracks, considerable efflorescence, or opened construction joints permitting loss of backfill. Considerable settlement or misalignment. Considerable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection throughout, extensive corrosion or deep pitting.
P 3	SERIOUS	Any condition described in Code 4 but which is excessive in scope. Severe movement or differential settlement of the segments, or loss of fill. Holes may exist in walls or slabs. Integral wingwalls, nearly severed from culvert. Severe scour or erosion at curtain walls, wingwalls, or pipes. Metal culverts have extreme distortion and deflection in one section, extensive corrosion, or deep pitting with scattered perforations.
C 2	CRITICAL	Advance deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C 1	"IMMINENT" FAILURE	Bridge closed. Corrective action may put back in light service.
0	FAILED	Bridge closed. Replacement necessary.

DEFICIENCY REPORTING GUIDE

DEFICIENCY: A defect in a structure that requires corrective action.

CATEGORIES OF DEFICIENCIES:

M= Minor Deficiency - (Examples include but are not limited to: Spalled concrete, minor to moderate corrosion to steel culverts, minor settlement or misalignment, minor scouring, minor damage to guardrail, etc.)

S= Severe/Major Deficiency - (Examples include but are not limited to: Large spalls, wide cracks, moderate to major deterioration in concrete, considerable settlement, considerable scouring or undermining, extensive corrosion and deflection in steel culverts, etc.)

C-S= Critical Deficiency - A deficiency in a structural component or element of a bridge that poses an extreme hazard or unsafe condition to the public. (Follow-up Critical Deficiency Report must be submitted separately)

URGENCY OF REPAIR:

I = Immediate - (Inspector(s) stay at the bridge until the District Maintenance crew or the responsible Agency crew (if not a State bridge) show up and corrective action is taken.)

A = ASAP - (Action will be taken by the District Maintenance Engineer or the Responsible Agency (if not a State owned bridge) upon receipt of the Inspection Report.)

P = Prioritize - (Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available.)

CITY/TOWN ACTON	B.I.N. 25B	BR. DEPT. NO. A-02-023	8.-STRUCTURE NO. A02023-25B-MUN-NBI	INSPECTION DATE JAN 6, 2006
---------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS

Item 62.11 - Sidewalks

A bit. conc. sidewalk has been installed since last inspection.

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.2 - Embankment Erosion

There is minor to moderate erosion of the channel embankments at the downstream SE corner, approx. 50 ft. downstream of the bridge. This is minor erosion at the SW & NW (upstream) corners that is starting to slightly dislodge several rip rap stones.

Item 61.3 - Debris

There is a very minor build up of alluvial material thru-out several areas of both barrels.

Item 61.5 - Utilities

The utilities are hidden below channel.

Item 61.7 - Aggradation

Re: Item #61.3.

APPROACHES

Approaches a - Appr. pavement condition

The bit. conc. approach pavement is new since last inspection..

Approaches b - Appr. Roadway Settlement

Re: Approaches: a.

Approaches c - Appr. Sidewalk Settlement

Re: Item #62.11.

Photo Log

Photo 1 : Chain link pedestrian barricade at E side of culvert (sidewalk side)

CITY/TOWN ACTON	B.L.N. 25B	BR. DEPT. NO. A-02-023	8.-STRUCTURE NO. A02023-25B-MUN-NBI	INSPECTION DATE JAN 6, 2006
--------------------	---------------	---------------------------	--	--------------------------------

PHOTOS




Photo 1: Chain link pedestrian barricade at E side of culvert (sidewalk side)

Report Date: October 23, 2007

State Information				Classification				Code	
BDEPT#	A02023	Agency Br.No.		(112) NBIS Bridge Length				Y	
Town	Acton			(104) Highway System				N	
B.I.N#	25B	AASHTO#	089.7	(26) Functional Class -	Urban Local			19	
		FHWA Select List#	N	(100) Defense Highway				0	
Structure Number	A0202325BMJNNB1			(101) Parallel Structure				N	
(5) Inventory Route	151000000			(102) Direction of Traffic -	2-way traffic			2	
(2) State Highway Department District	03			(103) Temporary Structure				N	
(3) County Code	017	(4) Place code	00380	(105) Federal Lands Highways				0	
(8) Features Intersected	WATER FORT POND BROOK			(110) Designated National Network				N	
(7) Facility Carried	HWY MARTIN ST			(20) Toll -	On free road			3	
(9) Location	0.8MI N OF MAYNARD TWN.LN			(21) Maintain -	Town Agency			03	
(11) Kilometerpoint	0000.386			(22) Owner -	Town Agency			03	
(12) Base Highway Network	N			(37) Historical Significance	built after 1949 presumed to be not eligi			Z	
(13) LRS Inventory Route & Subroute	000000000000			Condition				Code	
(18) Latitude	42 DEG 27 MIN	31.69 SEC		(58) Deck				N	
(17) Longitude	71 DEG 27 MIN	45.00 SEC		(59) Superstructure				N	
(98) Border Bridge State Code		Share	%	(60) Substructure				N	
(99) Border Bridge Structure No. #				(61) Channel & Channel Protection				7	
				(62) Culverts				7	
Structure Type and Material				Load Rating and Posting				Code	
(43) Structure Type Main:	Steel	Code	319	(31) Design Load -	H 20=M 16			4	
Culvert	Jointless bridge type:	Not applicable		(63) Operating Rating Method -	Allowable Stress (AS)			2	
(44) Structure Type Appr:		Code	000	(64) Operating Rating				31.7	
Other				(65) Inventory Rating Method -	Allowable Stress (AS)			2	
(45) Number of spans in main unit			002	(66) Inventory Rating				22.6	
(46) Number of approach spans			0000	(70) Bridge Posting				4	
(107) Deck Structure Type -	Not applicable	Code	N	(41) Structure -	Open			A	
(108) Wearing Surface / Protective System:				Appraisal				Code	
A) Type of wearing surface -	Not applicable=no deck	Code	N	(67) Structural Evaluation				8	
B) Type of membrane -	Not applicable=no deck	Code	N	(68) Deck Geometry				N	
Type of deck protection -	Not applicable=no deck	Code	N	(69) Underclearances, vert. and horiz.				N	
Age and Service				(71) Waterway adequacy				6	
(27) Year Built			1965	(72) Approach Roadway Alignment				7	
(106) Year Reconstructed			0000	(98) Traffic Safety Features			1 1 1	0	
(42) Type of Service: On -	Highway-Ped			(113) Scour Critical Bridges				6	
Under -	Waterway	Code	55	Inspections					
(26) Lanes: On Structure	02	Under structure	00	(90) Inspection Date	01/06/06	(91) Frequency	24	MO	
(26) Average Daily Traffic			003300	(92) Critical Feature Inspection:		(93) CF# DATE			
(30) Year of ADT	2006	(109) Truck ADT	06 %	(A) Fracture Critical Detail	N 00	MO A)		00/00/00	
(19) Bypass, detour length			002 KM	(B) Underwater Inspection	N 00	MO B)		07/01/85	
Geometric Data				(C) Other Special Inspection	N 00	MO C)		00/00/00	
(46) Length of maximum span			0002.7 M	(*) Other Inspection ()	N 00	MO *)		00/00/00	
(49) Structure Length			00008.4 M	(*) Closed Bridge	N 00	MO *)		00/00/00	
(50) Curb or sidewalk:	Left	00.0 M	Right	00.0 M	(*) UW Special Inspection	N 00	MO *)	00/00/00	
(51) Bridge Roadway Width Curb to Curb			000.0 M	(*) Damage Inspection		MO *)		00/00/00	
(52) Deck Width Out to Out			000.0 M	Rating Loads					
(32) Approach Roadway Width (w/shoulders)			007.9 M	Report Date	03/01/82	H20	Type 3	Type 3S2	Type HS
(33) Bridge Median -	No median	Code	0	Operating		20.0	32.0	50.0	0.0
(34) Skew	12 DEG	(35) Structure Flared	N	Inventory		17.0	23.0	38.0	0.0
(10) Inventory Route MIN Vert Clear			99.99 M	Field Posting					
(47) Inventory Route Total Horiz Clear			10.4 M	Status	WAIVED	Posting Date			07/21/82
(53) Min Vert Clear Over Bridge Rdwy			99.99 M	Actual	2 Axle	3 Axle	5 Axle		
(54) Min Vert Underclear ref	N		00.00 M	Recommended					
(55) Min Lat Underclear RT ref	N		00.0 M	Missing Signs	N				
(58) Min Lat Underclear LT			00.0 M	Misc.					
Navigation Data				Bridge Name	N Anti-missile fence	N Acrow Panel	N Jointless Bridge		
(3) Navigation Control -	No navigation control on waterway	Code	0	Freeze/Thaw	N : Not Applicable				
(1) Navigation Vertical Clearance		Code	000.0 M	Accessibility (Needed/Used)					
(116) Vert-Horiz Bridge Nav Min Vert Clear		M		N / N	Liftbucket	N / N	Rigging	Inspection	
(40) Navigation Horizontal Clearance		0000.0 M		N / N	Ladder	N / N	Staging	Hours:	008
				N / N	Boat	N / N	Traffic Control		
				Y / Y	Wader	N / N	RR Flagperson		
				N / N	Inspector 50	N / N	Police		

Blood Lab - know diff cell types & how to do blood typing .. draw pics.

Heart Lab- Draw and label - aorta, vena cave, pulm veins, valves, atriums and ventricles, septum, etc

EKG Lab- ekg machine, know PQRST when is what on the picture.. what do they mean

Respiratory System Lab- 2 vs. 3 lobes, primary secondary and tertiary bronchi, trachea, esophagus is behind trachea, thyroid cartilage (adams apple), tracheal cartilage, spirometer (name of the machine), diff volumes (tidal etc know what they mean) and be able to identify them on the picture of diff volumes.

Stomach Lab- on the model there is a green area that is the gall bladder. know liver, (little green area = bile duct), duodenum = sm intestine connects to stomach. (on models the white lines = pancreatic duct and vessels) know microvilli, LACTEAL is the indicator it is Sm intestines (she emphasized that) there was a model with layers. layers go mucosa - submucosa - muscular - serosa

Kidney Lab- draw and ID a picture of a kidney

Urinalysis and Urinary Sys Lab- draw and label urinary sys. (i cant find my urinalysis info, but all we did was stick strips into fake pee and determined which pee was normal, which had too much glucose, and which had too much something else)

Reproductive Sys Lab- prostate gland, 635 pic, 630 pic, ductus deferens, ejac. duct, prostate, bulb. gland.. etc.. just draw out pics and label them, but she was very insistant we know the prostate and prostate gland... and then all the female junk... and know placenta.
Cumulative breathe