



Exchange Hall
Bluebird Realty Trust

2 School Street
Acton, Massachusetts 01720
www.exchangehall.com
exchange.hall@verizon.net

March 15, 2011

Brona Simon
Massachusetts Historical Commission
220 Morrissey Boulevard, Boston, Ma 02125-3314

Re: Request for Certification of Completed Work
Historic Rehabilitation Tax Credit Program
Project Number: NPS 18142
Mass Historical Commission Project Number: 22927
Exchange Hall, (Bluebird Realty Trust) 2 School Street, Acton, MA 01720

Dear Ms Simon,

Enclosed please find the documentation of rehabilitation for Exchange Hall (Bluebird Realty Trust), which took place between November 10, 2008 and November 10, 2010.

- Included:
- 1) Copy of approved US Dept of Interior National Park Service application part 2.
 - 2) Mass Historical Commission, State Historic Rehabilitation Tax Credit Program, Historic Preservation Certification Application part 3 – Request for certification of completed work.
 - 4) Photographs of Exchange Hall prior to rehabilitation (both exterior and interior views).
 - 3) Photographs of Exchange Hall after completed work (both exterior and interior views). Floor plan key, using the same reference numbers as the pictures submitted with part 2, prior to rehabilitation.

Regarding the “Conditions Sheet” for the Preservation Certification Application:

- 1) Repointing – completed as requested.
- 2) Siding – manually scraped, sanded using a Massachusetts certified lead removal and disposal company. No power washing was used.
- 3) Railings – no cable railings installed.
- 4) Storm windows – restored original windows, no storm windows installed.
- 5) Addition – eliminated from design.
- 6) Tenant Improvements – tenant fit-out involved painting, floor sanding, electrical update, and plumbing update.

Please contact me if any additional information is required.

Sincerely,


Glenn Berger
Exchange Hall

**MASSACHUSETTS HISTORICAL COMMISSION
STATE HISTORIC REHABILITATION TAX CREDIT PROGRAM
HISTORIC PRESERVATION CERTIFICATION APPLICATION
PART 3 – REQUEST FOR CERTIFICATION OF COMPLETED WORK**

Exchange Hall
Property Name

2 School Street, Acton, MA 01720
Property Address

Project Number: NPS # 18142

Instructions. Upon completion of the rehabilitation, return this form with representative photographs of the completed work (both exterior and interior views) to the Massachusetts Historical Commission. A copy of this form will be provided to the Department of Revenue. Type or print clearly in black ink. The decision of the Massachusetts Historical Commission with respect to certification is made on the basis of the descriptions in this application form. In the event of any discrepancy between the application form and other, supplementary material submitted with it (such as architectural plans, drawings and specifications), the application form shall take precedence.

1. Name of property: Exchange Hall
 Address of property: Street 2 School Street
 City Acton County Middlesex State MA Zip 01720
 Is property a certified historic structure? yes no If yes, date of certification by MHC: _____
 or date of listing in the National Register: 6-13-1986

2. Data on rehabilitation project:
 Massachusetts Historical Commission assigned rehabilitation project number: # 22927
 Project starting date: November 10, 2008
 Rehabilitation work on this property was completed and the building placed in service on: November 10, 2010
 Estimated costs attributed solely to rehabilitation of the historic structure: \$ 610,019.00
 Estimated costs attributed to new construction associated with the rehabilitation, including additions, site work, parking lots, landscaping: \$ 0

3. Owner: (space below for additional owners)
 I hereby apply for certification of rehabilitation work described above for purposes of the State tax incentives. I hereby attest that the information provided is, to the best of my knowledge, correct, and that, in my opinion the completed rehabilitation meets the Secretary of the Interior's "Standards for Rehabilitation" and is consistent with the work described in the Description of Rehabilitation. I also attest that I own the property described above.
 Name Glenn Berger Signature [Signature] Date 3-16-2011
 Organization Exchange Hall LLC (previously Bluebird Realty Trust)
 Social Security or Taxpayer Identification Number 153-38-2532
 Street 2 School Street City Acton
 State Massachusetts Zip 01720 Daytime Telephone Number 978-263-0222

Additional Owners:
 Name _____
 Street _____ City _____
 State _____ Zip _____ Daytime Telephone Number _____
 Social Security or Taxpayer Identification Number _____

Name _____
 Street _____ City _____
 State _____ Zip _____ Daytime Telephone Number _____
 Social Security or Taxpayer Identification Number _____

NATIONAL PARK SERVICE

RECEIVED

HISTORIC PRESERVATION CERTIFICATION APPLICATION
PART 2 - DESCRIPTION OF REHABILITATION

NOV 28 2008

NPS Office Use Only

NRIS No:

RECEIVED
JAN 06 2009
NATIONAL PARK SERVICE
EXCISE PROGRAM

NPS Office Use Only

Pr

22927 MASS. HIST. COMM

Instructions: Read the instructions carefully before completing this application. No fee will be made unless a completed application form has been received. Type or print clearly in black ink. If additional space is needed, attach blank sheets. A copy of this form may be provided to the Internal Revenue Service. The decision by the National Park Service with respect to certification is made on the basis of the descriptions in this application form. In the event of any discrepancy between the application form and other, supplementary material submitted with it (such as architectural plans, drawings, and specifications), the application form shall take precedence.

1. Name of Property: Exchange Hall
Address of Property: Street 2 School Street
City Acton County Middlesex State MA Zip 01720
 Listed individually in the National Register of Historic Places; give date of listing: 6/13/1986
 Located in a Registered Historic District; specify:
Has a Part 1 Application (Evaluation of Significance) been submitted for this project? yes no
If yes, date Part 1 submitted: 1/17/2006 Date of certification: 4/13/2006 NPS Project Number: 18142

2. Data on building and rehabilitation project:
Date building constructed: 1860 Total number of housing units before rehabilitation: 0
Type of construction: Wood frame Number that are low-moderate income: NA
Use(s) before rehabilitation: Office/workshop/art studios/meeting hall Total number of housing units after rehabilitation: 0
Proposed use(s) after rehabilitation: Restaurant/function hall Number that are low-moderate income: NA
Estimated cost of rehabilitation: \$1,500,000 Floor area before rehabilitation: 10,251 s.f.
This application covers phase number 1 of 1 phases Floor area after rehabilitation: 12,187 s.f.
Project/phase start date (est.): 11-10-2008 Completion date (est.): 11-10-2010

3. Project contact:
Name Christine Beard/Tremont Preservation Services
Street 21 Market Street City Ipswich
State MA Zip 01938 Daytime Telephone Number 978-356-0322

4. Owner:
I hereby attest that the information I have provided is, to the best of my knowledge, correct, and that I own the property described above. I understand that falsification of factual representations in this application is subject to criminal sanctions of up to \$10,000 in fines or imprisonment for up to five years pursuant to 18 U.S.C. 1001.
Name Glenn Berger Signature *Glenn Berger* Date 11/10/08
Organization *Bluebird Realty Trust
Social Security or Taxpayer Identification Number
Street c/o Acton Woodworks, Inc. 2 School Street City Acton
State MA Zip 01720 Daytime Telephone Number 978-263-0222

NPS Office Use Only *Please fax a copy of the signed approval to Chris Beard at 978-356-0322.

The National Park Service has reviewed the "Historic Certification Application - Part 2" for the above-named property and has determined:
 that the rehabilitation described herein is consistent with the historic character of the property or the district in which it is located and that the project meets the Secretary of the Interior's "Standards for Rehabilitation." This letter is a preliminary determination only, since a formal certification of rehabilitation can be issued only to the owner of a "certified historic structure" after rehabilitation work is completed.
 that the rehabilitation or proposed rehabilitation will meet the Secretary of the Interior's "Standards for Rehabilitation" if the attached conditions are met.
 that the rehabilitation described herein is not consistent with the historic character of the property or the district in which it is located and that the project does not meet the Secretary of the Interior's "Standards for Rehabilitation." A copy of this form will be provided to the Internal Revenue Service.

Date 1/15/2009 National Park Service Authorized Signature *Orlinda Newberry* National Park Service Office Telephone No. NPS/TPS

See Attachments
Condition Sheet

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

CONDITIONS SHEET
Historic Preservation Certification Application

Property name: Exchange Hall

Project Number: 22927

Property address: 2 School Street, Acton, MA

The rehabilitation of this property as described in the Historic Preservation Certification Application will meet the Secretary of the Interior's Standards for Rehabilitation provided that the following condition(s) is/are met:

Repointing – Repointing mortar must match the color, texture, strength, joint width and joint profile of the existing historic masonry. Good quality overall and close-up color photographs of the masonry before and after repointing must be submitted with the Request for Certification of Completed Work.

Siding – Power washing the siding must not damage or alter the appearance of the siding and must not allow water into the wall cavity.

Railings – The cable railings to be added to meet code should be painted a darker neutral color to lessen their visibility.

Storm windows – The low-e storm panels must be clear, not tinted.

Addition – The windows on the addition must not have shutters in order to differentiate it from the historic building.

Tenant Improvements – This approval does not extend to tenant improvements, details of which have not been submitted for review and approval to the SHPO and this office. Federal regulations governing this program require evaluation of entire projects. Therefore, review of future tenant work by this office and the SHPO will also encompass all work proposed or completed up to that time. This approval may be superseded if it is found that the overall rehabilitation does not meet the Secretary's Standards. Please submit the additional information regarding tenant improvements as soon as available for review to ensure conformance of the overall project with the Standards.

The National Park Service has determined that this project will meet the Secretary of the Interior Standards for Rehabilitation if the condition(s) listed in the box above are met.

1/15/2009
Date

[Signature]
National Park Service Signature

NPS/TPS
Telephone Number



Acton Woodworks

2 School Street
Acton, MA 01720
978-263-0222
978-263-1873
info@actonwoodworks.com

Revision #7 12/20/10

Project #: 100927

CAD file:

Designer: Glenn Berger

Date: 10/30/08

Copyright: 2010

Builder: Acton Woodworks

Title


Exchange Hall
2 School Street
Acton MA, 01720

Restoration


Picture Reference #
Ground and First Floor
Plan

01

of 2



1. Ground Floor



2. First Floor



Acton Woodworks, Inc.
Residential Space Planning
Design and Build

Acton Woodworks

2 School Street
Acton, MA 01720
978-263-0222
978-263-1873
info@actonwoodworks.com

Revision #7 12/20/10

Project #: 100927

CAD file:

Designer: Glenn Berger

Date: 10/30/08

Copyright: 2010

Builder: Acton Woodworks


Title

Exchange Hall
2 School Street
Acton MA, 01720


Restoration

Picture Reference #-
Second and Third Floor
Plan



02 of 2







4. Third Floor (Ballroom)








3. Second Floor Plan


















































2/14




2



11




13




22A




21A






22B




22B




10




7



10A



6



9A



7

2, 7

4. Façade (south elevation) — detail of central entry

1, 2, 5, 6, 7

2, 3, 5, 6, 7

2. Façade (south elevation) — detail at lower level showing replacement doors

1, 2, 4, 5, 6, 7

3. Façade (south elevation) — detail at 1st floor showing new wood balustrade to match original

1. Façade (south elevation)

1, 2, 5, 6

1, 2, 4, 5, 6, 7

Architectural drawing showing a detail of a fire escape on the west elevation.

8. West elevation - detail of added fire escape

1, 2, 1

Architectural drawing showing a detail of a door on the west elevation at the former window location.

7. West elevation - detail of added door at north end (in former window location)

Architectural drawing showing a detail of the west elevation.

6. West elevation

2, 7

Architectural drawing showing a detail of the south elevation, specifically the entry area.

5. Façade (south elevation) - detail of east entry

1, 2, 7

4

REAR ELEVATION - NORTH SIDE - 1st FLOOR

14. Rear (north) elevation - detail of entry at 1st floor

1, 2, 4, 6, 7

4

REAR ELEVATION - NORTH SIDE - 1st FLOOR

13. Rear (north) elevation

REAR ELEVATION - NORTH SIDE - 1st FLOOR

16. First floor - view in stairhall at center of east wall

REAR ELEVATION - NORTH SIDE - 1st FLOOR

15. View along east wall showing stair between basement and first floor.

1, 2, 4

WEST ELEVATION - DETAIL OF ROOF LINE SHOWING DETERIORATION ABOVE CORNICE

10. West elevation - detail of roof line showing deterioration above cornice

2, 5

WEST ELEVATION - DETAIL OF SOUTH END SHOWING GRANITE REMAINING FROM FORMER STAIR

9. West elevation - detail of south end showing granite remaining from former stair

1, 2, 3, 4

EAST ELEVATION - DETAIL AT LOWER LEVEL

12. East elevation - detail at lower level

1, 2, 5, 4

EAST ELEVATION

11. East elevation

18. View toward second floor landing in stairhall

Faint, illegible text, possibly bleed-through from the reverse side of the page.

8

20. View of added egress stair from third floor

Faint, illegible text, possibly bleed-through from the reverse side of the page.

4

17. First floor – view in stairhall at south end of east wall

Faint, illegible text, possibly bleed-through from the reverse side of the page.

19. View toward third floor in stairhall

Faint, illegible text, possibly bleed-through from the reverse side of the page.

8

4

a

24. Ground floor – view toward southwest corner

VIEW TOWARD SW CORNER FROM SW CORNER

a

23. Ground floor – view along south wall showing replacement doors at entry

VIEW TOWARD SOUTH WALL FROM SW CORNER

22. View of stair at east end of balcony

VIEW TOWARD EAST END OF BALCONY FROM SW CORNER

21. Detail of added egress stair from third floor showing added doors

VIEW TOWARD EAST END OF BALCONY FROM SW CORNER

9

26. Ground floor - view toward southeast corner

26. Ground floor - view toward southeast corner

9

25. Ground floor - view northwest showing typical finishes

25. Ground floor - view northwest showing typical finishes

9

28. Ground floor - view north toward boiler room

28. Ground floor - view north toward boiler room

9

27. Ground floor - view near center of west wall

27. Ground floor - view near center of west wall

10

32. First floor -- view north along east side of building

32. First floor -- view north along east side of building

10

31. First floor -- view along south wall showing original entry doors

31. First floor -- view along south wall showing original entry doors

10

30. Ground floor -- view west in boiler room

30. Ground floor -- view west in boiler room

9

29. Ground floor -- view west in rear storage area

29. Ground floor -- view west in rear storage area

38. Second floor – view toward southeast corner

PHOTO TAKEN BY: [illegible]
DATE: [illegible]

10

PHOTO TAKEN BY: [illegible]
DATE: [illegible]

37. First floor – view in added bathroom along east wall

40. Second floor – view along west wall near center of building

PHOTO TAKEN BY: [illegible]
DATE: [illegible]

11

PHOTO TAKEN BY: [illegible]
DATE: [illegible]

39. Second floor – view in southwest corner showing added egress stair enclosure (right)

PHOTO TAKEN FROM ROOM 201
LOOKING WEST

42. Second floor -- view in room along west wall

PHOTO TAKEN FROM STAIRHALL
LOOKING EAST

41. Second floor - view at center of building
showing added partitions

PHOTO TAKEN FROM STAIRHALL
LOOKING WEST

44. Second floor -- view toward northwest corner
showing added bathroom partitions

PHOTO TAKEN FROM STAIRHALL
LOOKING WEST

43. Second floor -- view toward stairhall

12

50. Third floor – view toward northeast corner
showing added door at head of stairs

12

49. Third floor – view in room at center of rear
(north) wall

12

51. View toward east end of balcony