

June 5, 1972

Engineering Department

Planning Board

Drainage at 105 Arlington Street - James C. Walters

The problem is water running down Agawam Road and Arlington Street to a point just to the left of the Walters house. Here it runs into the Walters yard due to a low road shoulder. It is possible that reconstruction of Arlington Street (mix-in-place) a few years ago raised the road surface enough to create the problem.

With the transit we checked the pitch along Arlington Street and found except for one flat spot (about 15' long) there is a constant pitch to the road. If the road shoulder is raised with a couple loads of loam the water should run past the Walters property to a low wooded area where it should not be a problem.

David Alt