

ACTON SURVEY & ENGINEERING, INC.

JOHN E. DUNPHY, JR., President

P.O. BOX 666 • ACTON, MASS. 01720

October 28, 1980

Acton Engineering Department
Forest Road
Acton, MA 01720


RE: Tuttle Drive, Acton - David Moulton

Gentlemen:

Please be advised that the road bounds at Station 4+99.85 right and Station 8+30.04 right on Tuttle Drive were re-established on August 20, 1980, by this firm, based on the other road bounds in the area. The bound at Station 4+99.85 was replaced with a new concrete bound while the bound at Station 8+30.04 was recovered and adjusted.

Very truly yours,

ACTON SURVEY & ENGINEERING, INC.



John E. Dunphy, Jr., President

JED:p

cc: David Moulton



File No. 968