



FILE COPY

TOWN OF ACTON, MA 01720  
DEPARTMENT OF PUBLIC WORKS

David W. Perley  
140 Commerford Rd.  
Concord, MA 01742

October 15, 1986

80-32

Dear Mr. Perley,

The Town of Acton is currently holding two bonds from L&S Builders Corporation for work done under "Permits to Construct Within a Public Way" numbers 80-32 and 82-68. The work which remains to be done involves resetting three road bounds. (see enclosed plan) Two of these bounds are on the rounding at Gristmill Road and Windemere Drive on lot 61, the other is at the P.T. in front of lot 59.

Recently, we inspected both sites and found that the bounds on lot 61 were significantly off from the plan location, and the bound in front of lot 59 was missing. We also noticed that several P.K. nails along the center-line of Gristmill Road had been exposed, primarily at the P.C.'s, P.T.'s and the center-line intersection of Windemere Drive.

We would like to know if these are the original nails from which the bounds were set so that we can use them to reset the bounds if you are not planning to do so. Any supporting calculations you have would also be appreciated.

If you have any questions, please feel free to contact me at 264-9628.

Sincerely,

David F. Abbt  
Engineering Administrator

cc: Al Soma  
L&S Builders