


12/18/21
12


APPENDIX C

APPENDIX C:

Site Photographs




1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to northeast. Photo taken southwest of the Site from Massachusetts Avenue. Photo depicts the south portion of the Site building.



1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. Photo taken south of the Site building. Photo depicts a sprinkler shut-off valve.




1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to east. Photo taken west of the Site across Charter Road. Photo depicts the west portion of the Site building.




1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. Photo taken west of the Site building. Photo depicts a pad-mounted transformer situated along the west portion of the Site building.




1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to southwest. Photo taken northeast of the Site building from a newly developed access road. Photo depicts the north and east portions of the Site building.



1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to west. Photo taken east of the Site building. Photo depicts a portion of the playground as well as the east and north portions of the Site building.



1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to west. Photo taken east of the Site building. Photo depicts the east portion of the Site building, playground and the south portion of the Site.



1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to west. Photo taken east of the Site building. Photo depicts a chain-linked fence enclosing a gas meter situated near the northeast corner of the Site building.



1176-2010 11/12/02: Three Charter Road, Acton, Massachusetts. View to west. Photo taken east of the Site building and south of the gas meter. Photo depicts a sewer clean out pipe.