

Legend

1. Abandoned Railroad Tracks
2. Railroad Easement
3. Wetlands
4. Granite Marker
5. Existing Walkway
6. Existing Vegetation/Ledge Outcroppings

ELLSWORTH JUNCTION

EAST ACTON, MASSACHUSETTS

EXISTING CONDITIONS

PREPARED BY THE CECIL GROUP INC.
MASS. DEPARTMENT OF HOUSING AND COMMUNITY DEVELOPMENT
EAST ACTON VILLAGE PLANNING COMMITTEE